

Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-10845 (63 FR 55783), and by adding a new airworthiness directive (AD), Amendment 39-11397, to read as follows:

AD 99-23-01 Robinson Helicopter

Company: Amendment 39-11397.

Docket No. 99-SW-12-AD. Supersedes AD 98-21-36, Amendment 39-10845, Docket No. 97-SW-01-AD.

Applicability: Model R44 helicopters, serial numbers (S/N) 0001 through 0159, except S/N's 0143, 0150, and 0156, with pilot's cyclic control grip assembly (grip assembly), part number (P/N) A756-6, Revision N or prior revision, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Within 25 hours time-in-service or 30 calendar days, whichever occurs first, unless accomplished previously.

To prevent use of a grip assembly that may crack, resulting in failure of the grip assembly and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove the grip assembly, P/N A756-6, Revision A through N, and replace it with an airworthy grip assembly other than P/N A756-6, Revision A through N.

Note 2: Robinson KI-112 R44 Pilot's Grip Assembly Upgrade Kit instructions, dated December 20, 1996, pertain to the subject of this AD.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Los Angeles Aircraft Certification Office.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles Aircraft Certification Office.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on December 8, 1999.

Issued in Fort Worth, Texas, on October 26, 1999.

Eric Bries,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 99-28655 Filed 11-2-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-SW-60-AD; Amendment 39-11398; AD 99-23-02]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model SA-365N, SA-365N1, and AS-365N2 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to Eurocopter France Model SA-365N, SA-365N1, and AS-365N2 helicopters, that requires replacing certain defective electrical modules with airworthy electrical modules. This amendment is prompted by the discovery of several defective electrical modules. The actions specified by this AD are intended to prevent loss of electrical continuity, which could cause loss of critical rotorcraft electrical systems and subsequent loss of control of the helicopter.

EFFECTIVE DATE: December 8, 1999.

FOR FURTHER INFORMATION CONTACT: Robert McCallister, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5121, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that is applicable to Eurocopter France Model SA-365N, SA-365N1, and AS-365N2 helicopters was published in the **Federal Register** on August 4, 1999 (64 FR 42295). That

action proposed to require replacing certain defective electrical modules with airworthy electrical modules.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for two nonsubstantive changes that have been made to paragraph (b) and Note 3 of the AD. In paragraph (b), the NPRM incorrectly states that alternative methods of compliance (AMOC) or adjustments of the compliance time may be approved by the "Manager, Rotorcraft Standards Staff, Rotorcraft Directorate." This is incorrect and has been changed to state that the Manager, Regulations Group, Rotorcraft Directorate, is responsible for approving any AMOC or adjustment of the compliance time. Note 3 of the NPRM states that information concerning the existence of approved AMOC may be obtained from the "Rotorcraft Standards Staff"; this is also incorrect and has been changed to state that information may be obtained from the "Regulations Group." The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 41 helicopters of U.S. registry will be affected by this AD, that it will take approximately 300 work hours per helicopter to replace all affected modules, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$29,520, but the helicopter manufacturer has stated that the parts will be provided at no cost. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$738,000 to replace all affected modules.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3)

will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

AD 99-23-02 Eurocopter France:

Amendment 39-11398. Docket No. 98-SW-60-AD.

Applicability: Model SA-365N, SA-365N1, and AS-365N2 helicopters, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within 200 hours time-in-service (TIS) or within the next 3 calendar months, whichever occurs first, unless accomplished previously.

To prevent loss of electrical continuity, which could cause loss of critical rotorcraft electrical systems and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove and replace each "CONNECTRAL" green electrical module that does not have a white dot on the face

and that has a manufacturing code of 95/16 through 96/21 with an airworthy electrical module.

Note 2: Eurocopter France Service Bulletin No. 01.00.47R1, dated December 18, 1998, pertains to the subject of this AD.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA.

Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on December 8, 1999.

Note 4: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD No. 1998-253-044(A)R1, dated February 10, 1999.

Issued in Fort Worth, Texas, on October 26, 1999.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 99-28654 Filed 11-2-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-ACE-46]

Amendment to Class E Airspace; Mountain View, MO

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This action amends Class E airspace area at Mountain View Airport, Mountain View, MO. A review of the Class E airspace area for Mountain View Airport indicates it does not comply with the criteria for 700 feet Above Ground Level (AGL) airspace required for diverse departures as specified in FAA Order 7400.2D. The Class E airspace has been enlarged to conform to the criteria of FAA Order 7400.2D.

In addition, a minor revision to the Airport Reference Point (ARP) is included in this document.

The intended effect of this rule is to provide additional controlled Class E

airspace for aircraft operating under Instrument Flight Rules (IFR), revise the ARP, and comply with the criteria of FAA Order 7400.2D.

DATES: Effective date: 0901 UTC, February 24, 2000.

Comments for inclusion in the Rules Docket must be received on or before December 5, 1999.

ADDRESSES: Send comments regarding the rule in triplicate to: Manager, Airspace Branch, Air Traffic Division, ACE-520, DOT Regional Headquarters Building, Federal Aviation Administration, Docket Number 99-ACE-46, 901 Locust, Kansas City, MO 64106.

The official docket may be examined in the Office of the Regional Counsel for the Central Region at the same address between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

An informal docket may also be examined during normal business hours in the Air Traffic Division at the same address listed above.

FOR FURTHER INFORMATION CONTACT:

Kathy Randolph, Air Traffic Division, Airspace Branch, ACE-520C, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329-2525.

SUPPLEMENTARY INFORMATION: This amendment to 14 CFR 71 revises the Class E airspace at Mountain View, MO. A review of the Class E airspace for Mountain View Airport, MO, indicates it does not meet the criteria for 700 feet AGL airspace required for diverse departures as specified in FAA Order 7400.2D. The criteria in FAA Order 7400.2D for an aircraft to reach 1200 feet AGL is based on a standard climb gradient of 200 feet per mile plus the distance from the ARP to the end of the outermost runway. Any fractional part of a mile is converted to the next higher tenth of a mile. The amendment at Mountain View Airport, MO, will provide additional controlled airspace for aircraft operating under IFR, revise the ARP, and comply with the criteria of FAA Order 7400.2D. The area will be depicted on appropriate aeronautical charts. Class E airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9G, dated September 10, 1999, and effective September 16, 1999, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.