

required only in total for each Harmonized Tariff Schedule code. Importers are still permitted to report the scientific name information by article or component of article if that organizational structure is preferable. This has significantly reduced the lines of data entry required while causing little reduction in the enforcement utility of the information. However, the importer of record is still required to maintain records documenting the information used to calculate these total amounts for 5 years, should it be needed to facilitate an inspection or substantiate the totals provided.

The declaration could also be revised to substitute a new term in place of the term "country of harvest," which experience has indicated is so similar to the Customs term "country of origin" as to be confusing. We are considering using the phrase "harvest location (by country)" to attempt to more clearly distinguish this information from the Customs concept of country of origin of the merchandise.

The declaration form could be further revised to accommodate the changes and proposals described above. These changes could include revision of the form to collect information required for composite materials (the percent composite material in the shipment, for which it is not possible to identify species and/or country of harvest). In addition, the revised form could have a box that would have to be checked when an importer needs to report goods manufactured prior to May 22, 2008, for which the importer cannot determine, in the exercise of due care, the genus, species and/or country of harvest of those plant products. The box would state that the plant products were manufactured prior to May 22, 2008, and that in the exercise of due care, the importer has been unable to determine the genus, species, and/or country of harvest information that is lacking on the declaration form.

We are soliciting comments on these possible changes to the declaration form.

Declaration of Genus and Species Using Species Groupings

We also recognize that the declaration requirement to identify the genus and species of all plants that may be contained in covered products may frequently require declarations to contain long lists of species. A number of commenters requested that recognized groups of common species often traded in combination in similar percentages in particular industries be allowed to be declared under a single shorthand definition. In a previous

notice we specifically invited comments on the use of species groups, such as "SPF" for spruce, pine and fir, when such groups accurately describe the species that may be contained in the product(s) covered by the declaration. We received a number of comments supporting this approach and no comments in opposition. Therefore, we have begun to provide reference codes for such groups, along with the lists of species included in each group, on the APHIS Web site at http://www.aphis.usda.gov/plant_health/lacey_act/.

In addition, we invite proposals for additional groupings to be considered. Any proposal for a species group should contain the complete list of species to be included and additional information with which we can evaluate the extent to which the proposed group is currently represented in goods in international trade. Only those species group codes posted on the APHIS Web site can be used to meet the requirement to provide genus and species information on the plant import declaration.

The Web site also contains the text of the Lacey Act, as amended, the declaration form and enforcement schedule, guidance on compliance with the provisions of the Act, and links to previous **Federal Register** publications. The Web site will be updated as new materials become available.

Persons interested in receiving updates on APHIS's Lacey Act efforts should register for our stakeholder registry at <https://web01.aphis.usda.gov/PPQStakeWeb2.nsf> and select "Lacey Act Declaration" as a topic of interest.

This action has been determined to be not significant for the purposes of Executive Order 12866 and, therefore, has not been reviewed by the Office of Management and Budget.

Authority: 16 U.S.C. 3371 *et seq.*; 7 CFR 2.22, 2.80, and 371.2(d).

Done in Washington, DC, this 24th day of June 2011.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 2011-16406 Filed 6-29-11; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-0649; Directorate Identifier 2011-NM-076-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Model MD-11 and MD-11F Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD would require replacing the rub strips of the tail fuel tank access door with new rub strips. This proposed AD was prompted by a report that the rub strips of the tail fuel tank access door were manufactured improperly. We are proposing this AD to prevent inadequate electrical bonding between the rub strips and the fuel access door, which can contribute to possible ignition of flammable fuel vapor in the tail fuel tank as a result of a lightning strike.

DATES: We must receive comments on this proposed AD by August 15, 2011.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; e-mail dse.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Philip Kush, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; phone: 562-627-5263; fax: 562-627-5210; e-mail: philip.kush@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-0649; Directorate Identifier 2011-

NM-076-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received a report that the rub strips of the tail fuel tank access door were manufactured improperly. These rub strips were inadvertently anodized (electrically non-conductive) instead of alodined (electrically conductive) as prescribed in design drawings. Anodization of the rub strips may prevent adequate electrical bonding between the rub strips and the doors. Inadequate electrical bonding can contribute to possible ignition of flammable fuel vapor in the tail fuel tank as a result of a lightning strike.

Relevant Service Information

We reviewed Boeing Special Attention Service Bulletin MD11-55-027, dated March 17, 2011. The service information describes procedures for replacing the rub strips of the tail fuel tank access door with new rub strips. Replacing anodized rub strips with alodined rub strips will provide adequate electrical bonding between the rub strips and the fuel access doors.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 120 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace rub strips	32 work-hours × \$85 per hour = \$2,720	\$0	\$2,720	\$326,400

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2011-0649; Directorate Identifier 2011-NM-076-AD.

Comments Due Date

(a) We must receive comments by August 15, 2011.

Affected ADs

(b) None.

Applicability

(c) The Boeing Company Model MD-11 and MD-11F airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin MD11-55-027, dated March 17, 2011.

Subject

(d) Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 5510: Tail Fuel Tank Access Door.

Unsafe Condition

(e) This AD was prompted by a report that the rub strips of the tail fuel tank access door were manufactured improperly. We are issuing this AD to prevent inadequate electrical bonding between the rub strips and the fuel access door, which can contribute to possible ignition of flammable fuel vapor in the tail fuel tank as a result of a lightning strike.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Installation

(g) Within 60 months after the effective date of this AD, replace the rub strips of the tail fuel tank access door with new rub strips, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin MD11-55-027, dated March 17, 2011.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

Related Information

(i) For more information about this AD, contact Philip Kush, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, California 90712-4137; phone: 562-627-5263; fax: 562-627-5210; e-mail: philip.kush@faa.gov.

(j) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long

Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; e-mail dse.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 22, 2011.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011-16479 Filed 6-29-11; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY**40 CFR Part 52**

EPA-R03-OAR-2010-0475; FRL-9426-3J

Approval and Promulgation of Air Quality Implementation Plans; District of Columbia, Maryland, and Virginia; 2002 Base Year Emission Inventory, Reasonable Further Progress Plan, Contingency Measures, Reasonably Available Control Measures, and Transportation Conformity Budgets for the Washington, DC Area 1997 8-Hour Moderate Ozone Nonattainment Area

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve State Implementation Plan (SIP) revisions submitted by the District of Columbia, the State of Maryland, and the Commonwealth of Virginia (the States). These revisions pertain to the 2002 base year emissions inventory, the reasonable further progress (RFP) plan, RFP contingency measure, and reasonably available control measure (RACM) requirements of the Clean Air Act (CAA) for the Washington, DC area moderate 1997 8-hour ozone nonattainment area (Washington Area). EPA is also proposing to approve the transportation conformity motor vehicle emissions budgets (MVEBs) associated with this revision. EPA is proposing to approve the SIP revisions because they satisfy the emission inventory, RFP, RACM, RFP contingency measures, and transportation conformity requirements for areas classified as moderate nonattainment for the 1997 8-hour ozone national ambient air quality standard (NAAQS) and demonstrate further progress in reducing ozone precursors. This action is being taken under the CAA.

DATES: Written comments must be received on or before August 1, 2011.

ADDRESSES: Submit your comments, identified by Docket ID Number EPA-R03-OAR-2010-0475 by one of the following methods:

A. www.regulations.gov. Follow the on-line instructions for submitting comments.

B. *E-mail:*

fernandez.cristina@epa.gov.

C. *Mail:* EPA-R03-OAR-2010-0475, Cristina Fernandez, Associate Director, Office of Air Program Planning, Mailcode 3AP30, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103.

D. *Hand Delivery:* At the previously-listed EPA Region III address. Such deliveries are only accepted during the Docket's normal hours of operation, and special arrangements should be made for deliveries of boxed information.

Instructions: Direct your comments to Docket ID No. EPA-R03-OAR-2010-0475. EPA's policy is that all comments received will be included in the public docket without change, and may be made available online at <http://www.regulations.gov>, including any personal information provided, unless the comment includes information claimed to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Do not submit information that you consider to be CBI or otherwise protected through <http://www.regulations.gov> or e-mail. The <http://www.regulations.gov> Web site is an "anonymous access" system, which means EPA will not know your identity or contact information unless you provide it in the body of your comment. If you send an e-mail comment directly to EPA without going through <http://www.regulations.gov>, your e-mail address will be automatically captured and included as part of the comment that is placed in the public docket and made available on the Internet. If you submit an electronic comment, EPA recommends that you include your name and other contact information in the body of your comment and with any disk or CD-ROM you submit. If EPA cannot read your comment due to technical difficulties and cannot contact you for clarification, EPA may not be able to consider your comment. Electronic files should avoid the use of special characters, any form of encryption, and be free of any defects or viruses.

Docket: All documents in the electronic docket are listed in the <http://www.regulations.gov> index.