

Issued in Washington, DC, on December 23, 2011.

Kathleen B. Hogan,

Deputy Assistant Secretary for Energy Efficiency, Energy Efficiency and Renewable Energy.

[FR Doc. 2012-328 Filed 1-10-12; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-1453; Directorate Identifier 2009-SW-46-AD]

RIN 2120-AA64

Airworthiness Directives; Agusta S.p.A. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Agusta S.p.A. (Agusta) Model A109, A109A, A109A II, A109C, A109K2, A109E, A109S, and A119 helicopters. This proposed AD is prompted by a mandatory continuing airworthiness information (MCAI) AD issued by the European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community. The MCAI AD states that a Model A109E helicopter has experienced a failure of the tail rotor pitch control link assembly caused by a production defect. The proposed actions are intended to prevent failure of a tail rotor pitch control link and subsequent loss of control of the helicopter.

DATES: We must receive comments on this proposed AD by March 12, 2012.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in

person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed AD, contact Agusta Westland, Customer Support & Services, Via Per Tornavento 15, 21019 Somma Lombardo (VA) Italy, ATTN: Giovanni Cecchelli; telephone 39 (0331) 711133; fax 39 (0331) 711180; or at <http://www.agustawestland.com/technical-bulletins>. You may review copies of the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

FOR FURTHER INFORMATION CONTACT: Gary Roach, Aerospace Engineer, Rotorcraft Directorate, Regulations and Policy Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email gary.b.roach@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2006-0228-E, dated July 27, 2006, to correct an unsafe condition for Agusta Model A109A, A109A II, A109C, A109K2, A109E, A109S, A109LUH and A119 helicopters. The MCAI AD states that an Agusta Model A109E helicopter has experienced a failure of the tail rotor pitch control link assembly, part number 109-0130-05-117, with 10 flight hours. This proposed AD would require actions that are intended to prevent failure of a tail rotor pitch control link and subsequent loss of control of the helicopter. You may obtain further information by examining the MCAI AD and any related service information in the AD Docket.

FAA's Determination

These products have been approved by the aviation authority of Italy and are approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, the EASA, their technology agents have notified us of the unsafe condition described in the MCAI AD and service information. We are proposing this AD because we evaluated all information provided by the EASA and determined the unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Related Service Information

Agusta has issued Alert Bollettino Tecnico (ABT) No. 109S-5, dated July 26, 2006, for Model A109S helicopters; ABT No. 109EP-70, dated July 27, 2006, for Model A109E helicopters; ABT No. 109K-47, dated July 27, 2006, for Model A109K2 helicopters; ABT No. 109-122, dated July 27, 2006, for Model A109A, A109A II, and A109C helicopters; and ABT No. 119-15, dated July 27, 2006, for Model A119 helicopters. These ABTs specify performing a one-time inspection of the subject link assembly for excessive friction of the spherical bearing of the bearing ball and for a crack. The EASA classified these ABTs as mandatory and issued EASA AD 2006-0228-E, to ensure the continued airworthiness of these helicopters.

Proposed AD Requirements

This proposed AD would require compliance with specified portions of the manufacturer's service bulletin including:

- Before further flight, inspect the affected link assembly for freedom of movement of the links while it is installed on the helicopter. If a rotation

resistance or binding occurs, before further flight, remove the link assembly from the helicopter, and either:

- Replace it with an airworthy link assembly with a “T” marked after the serial number, or
- Inspect the link assembly for the torsion value force of the ball bearing.
- If not immediately required by the previous paragraph, within 5 hours time-in-service, remove the link assembly from the helicopter and inspect the torsion value force of the ball bearing rotation.
- If the torsion value force in either end of the link assembly is greater than 7.30 N, the link assembly is unairworthy.
- If the torsion value force of the ball bearing in both ends of the link assembly is equal to or less than 7.30 N, inspect the stem of the link assembly for a crack. If a crack is found, the link assembly is unairworthy.
- For a link assembly that has been inspected and determined not to have a crack, before further flight, mark a “T” on the link assembly after the serial number using an etch pen.
- For a link assembly which has been inspected and determined to be unairworthy, before further flight, replace the link assembly with an airworthy link assembly. Only a link assembly with a “T” marked after the serial number, documenting that the link assembly has been inspected for a crack, is eligible for installation.

Differences Between This Proposed AD and the EASA AD

This proposed AD does not apply to uninstalled parts whereas the EASA AD does apply to uninstalled parts. This proposed AD includes the Agusta Model A109 helicopter whereas the EASA AD does not. The EASA AD applies to the Model A109LUH helicopter, this proposal does not. This proposed AD does not require accomplishing Part III of the ABTs; the EASA AD does.

Costs of Compliance

We estimate that this proposed AD would affect 203 helicopters of U.S. Registry.

We estimate that operators may incur the following costs in order to comply with this AD. It would take about 5 work-hours per helicopter to inspect each tail rotor pitch control link assembly, the average labor rate is \$85 per work-hour, and required parts would cost about \$3,188 per helicopter. Based on these figures, we estimate the total cost to be \$733,439, assuming the tail rotor pitch control link assembly would be replaced on the entire fleet.

According to the production approval holder’s (PAH’s) service information some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage by the PAH. Accordingly, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new Airworthiness Directive (AD):

Agusta S.p.A.: Docket No. FAA–2011–1453; Directorate Identifier 2009–SW–46–AD.

(a) Applicability

This AD applies to Agusta S.p.A. (Agusta) Model A109, A109A, A109A II, A109C, A109K2, A109E, A109S, and A119 helicopters, with a tail rotor pitch control link assembly (link assembly), part number (P/N) 109–0130–05–117, with less than 100 hours time-in-service (TIS) and with a serial number (S/N) with a prefix of “MO” and S/N 001 through 773 and without the letter “T” suffix after the S/N, installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a failure of the tail rotor pitch control link assembly P/N 109–0130–05–117. This condition could result in failure of the tail rotor pitch control link and subsequent loss of control of the helicopter.

(c) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(d) Required Actions

(1) Before further flight, inspect the link assembly for freedom of movement while it is installed on the helicopter. If rotation resistance or binding occurs, before further flight, remove the link assembly from the helicopter, and either:

- (i) Replace it with an airworthy link assembly with a “T” marked after the serial number, or;
- (ii) Inspect the link assembly for the torsion value force of the ball bearing rotation, in accordance with paragraph (d)(2) of this AD.

(2) If there is no rotation resistance or binding found during the inspection required by paragraph (d)(1) of this AD that required an immediate torsion value force inspection, within 5 hours TIS, remove the link assembly from the helicopter and inspect the torsion value force of the ball bearing rotation by referring to Figure 1 and following the

Compliance Instructions, Part II, paragraphs 3. through 3.2, of Agusta Alert Bollettino Tecnico (ABT) No. 109S-5, dated July 26, 2006, for Model A109S helicopters; ABT No. 109EP-70, dated July 27, 2006, for Model A109E helicopters; ABT No. 109K-47, dated July 27, 2006, for Model A109K2 helicopters; ABT No. 109-122, dated July 27, 2006, for Model A109, A109A, A109A II, and A109C helicopters; or ABT No. 119-15, dated July 27, 2006, for Model A119 helicopters.

(i) If the torsion value force of the ball bearing in either end of the link assembly is greater than 7.30 N, the link assembly is unairworthy.

(ii) If the torsion value force of the ball bearing in both ends of the link assembly is equal to or less than 7.30 N, after cleaning the link assembly stem using aliphatic naphtha, or equivalent, and a soft non-metallic bristle brush, inspect all 4 (four) faces of the stem of the link assembly for a crack using a 10x or higher magnifying glass. If you cannot determine whether there is a crack in the stem of the link assembly by using a 10x or higher magnifying glass, conduct a dye penetrant inspection by referring to Figure 1 and following the Compliance Instructions, Part II, paragraphs 6. through 6.7, of the ABT that is applicable to your model helicopter. If a crack is found, the link assembly is unairworthy.

(3) For a link assembly which has been inspected in accordance with paragraph (d)(2)(ii) of this AD and determined to be unairworthy, before further flight, replace the link assembly with an airworthy link assembly. Only a link assembly with a "T" marked after the serial number, documenting that the link assembly has been inspected for a crack, is eligible for installation.

(e) Alternative Methods of Compliance (AMOC)

(1) The Manager, Safety Management Group, Rotorcraft Directorate, FAA, may approve AMOCs for this AD. Send your proposal to: Gary Roach, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email gary.b.roach@faa.gov.

(2) For operations conducted under a Part 119 operating certificate or under Part 91, Subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(f) Additional Information

The subject of this AD is addressed in the European Aviation Safety Agency (Italy) AD 2006-0228-E, dated July 27, 2006.

(g) Subject

Joint Aircraft Service Component (JASC) Code: 6400: Tail Rotor System.

Issued in Fort Worth, Texas, on December 27, 2011.

M. Monica Merritt,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2012-367 Filed 1-10-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2011-0117; Airspace Docket No. 09-AGL-31]

RIN 2120-AI92

Proposed Establishment of Restricted Areas R-5402, R-5403A, R-5403B, R-5403C, R-5403D, R-5403E, R-5403F; Devils Lake, ND

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); extension of comment period.

SUMMARY: This action extends the comment period for an NPRM that was published on November 28, 2011. In that document, the FAA proposed to establish restricted area airspace within the Devils Lake East Military Operations Area (MOA), overlying Camp Grafton Range, in the vicinity of Devils Lake, ND. This extension is a result of a request from the North Dakota Aviation Council (NDAC), representing eight member groups including the Airport Association of North Dakota, North Dakota Business Aviation Association, North Dakota Pilots Association, North Dakota Professional Aviation Mechanics Association, and North Dakota Flying Farmers, to extend the comment period to the proposal.

DATES: The comment period for the NPRM published on November 28, 2011 (76 FR 72869), scheduled to close on January 12, 2012, is extended until February 12, 2012.

ADDRESSES: You may send comments identified by Docket Number FAA-2011-0017 and Airspace Docket No. 09-AGL-31 using any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Send comments to U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Fax:* Fax comments to Docket Operations at (202) 493-2251.

- *Hand Delivery:* Bring comments to U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Privacy: We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. Using the search function of our docket Web site, anyone can find and read the comments received into any of our dockets, including the name of the individual sending the comment (or signing the comment for an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78) or you may visit <http://DocketsInfo.dot.gov>.

Docket: To read background documents or comments received, go to <http://www.regulations.gov> at any time or to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Colby Abbott, Airspace, Regulations and ATC Procedures Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591, telephone (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, please send only one copy of written comments, or if you are filing comments electronically, please submit your comments only one time.

We will file in the docket all comments we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.