

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-06-02 The Boeing Company:

Amendment 39-17806; Docket No. FAA-2013-0089; Directorate Identifier 2012-NM-166-AD.

(a) Effective Date

This AD is effective April 25, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-400 series airplanes, certificated in any category, as identified in Boeing Service Bulletin 747-24A2360, Revision 2, dated October 2, 2013.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

(e) Unsafe Condition

This AD was prompted by reports of auxiliary power unit (APU) faults due to power feeder cable chafing. We are issuing this AD to detect and correct chafing of the APU power feeder cables within a flammable fluid leakage zone, which, with arcing, could result in fire and structural damage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection, Related Investigative and Corrective Actions

Within 18 months after the effective date of this AD: Do a detailed inspection for damage (e.g., surface finish integrity, excessive wear or possible heat damage) of the APU power feeder cables within each wire bundle on the left and right sides of the bulkhead, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-24A2360, Revision 2, dated October 2, 2013; except as required by paragraph (h) of this AD. If no damage is found during this inspection, before further flight, replace the clamp(s) and install grommets, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-24A2360, Revision 2, dated October 2, 2013. Do all applicable related investigative and correction actions before further flight. Where Boeing Service Bulletin 747-24A2360, Revision 2, dated October 2, 2013, specifies installation of a clamp having part number (P/N) TA025097L16, a clamp having P/N TA025097L() may be installed instead.

Note 1 to paragraph (g) of this AD: The parenthesis “()” designates different size

clamps, to accommodate possible wire bundle diameter size differences.

(h) Exceptions to the Service Information

If any damage is found during any inspection required by this AD, and Boeing Service Bulletin 747-24A2360, Revision 2, dated October 2, 2013, specifies to contact Boeing for appropriate action: Before further flight, repair the damage using a method approved in accordance with paragraph (k) of this AD.

(i) Parts Installation Limitation

As of the effective date of this AD, no person may install, on any airplane, any wiring support clamp, except for part number TA025097L(), in those areas of the airplane identified in Boeing Service Bulletin 747-24A2360, Revision 2, dated October 2, 2013.

Note 2 to paragraph (i) of this AD: The parenthesis “()” designates different size clamps, to accommodate possible wire bundle diameter size differences.

(j) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 747-24A2360, dated January 18, 2012; or Boeing Alert Service Bulletin 747-24A2360, Revision 1, dated May 2, 2012; which are not incorporated by reference in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(l) Related Information

(1) For more information about this AD, contact Georgios Roussos, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, Seattle Aircraft Certification Office, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6482; fax: 425-917-6590; email: georgios.roussos@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference may be obtained at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 747-24A2360, Revision 2, dated October 2, 2013.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 7, 2014.

Michael J. Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-06004 Filed 3-20-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-1057; Directorate Identifier 2013-CE-041-AD; Amendment 39-17805; AD 2014-06-01]

RIN 2120-AA64

Airworthiness Directives; M7 Aerospace LLC Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all M7 Aerospace LLC Models SA226-AT, SA226-T, SA226-T(B), SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, SA227-DC (C-26B), SA227-TT, SA26-AT, and SA26-T airplanes. This AD was

prompted by reports of airplanes with multiple fatigue cracks in the FS 69.31 front pressure bulkhead. This AD requires repetitively inspecting (visually) the FS 51.31 front pressure bulkhead on SA26 series airplanes and FS 69.31 front pressure bulkhead on SA226 and SA227 series airplanes for cracks, and repairing any cracked bulkhead; this AD also requires reporting certain inspection results to M7 Aerospace LLC. We are issuing this AD to correct the unsafe condition on these products.

DATES: This AD is effective April 25, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 25, 2014.

ADDRESSES: For service information identified in this AD, contact M7 Aerospace LP, 10823 NE Entrance Road, San Antonio, Texas 78216; phone: (210) 824-9421; fax: (210) 804-7766; Internet: <http://www.elbitsystems-us.com>; email: none. You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call 816-329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2013-1057; or in person at the Docket

Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Andrew McAnaul, Aerospace Engineer, FAA, ASW-150 (c/o San Antonio MIDO), 10100 Reunion Place, Suite 650, San Antonio, Texas 78216; phone: (210) 308-3365; fax: (210) 308-3370; email: andrew.mcanaul@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all M7 Aerospace LLC Models SA226-AT, SA226-T, SA226-T(B), SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, SA227-DC (C-26B), SA227-TT, SA26-AT, and SA26-T airplanes. The NPRM published in the **Federal Register** on December 24, 2013 (78 FR 77618). The NPRM was prompted by reports of airplanes with multiple fatigue cracks in the FS 69.31 front pressure bulkhead. The NPRM proposed to require repetitively inspecting

(visually) the FS 51.31 front pressure bulkhead on SA26 series airplanes and FS 69.31 front pressure bulkhead on SA226 and SA227 series airplanes for cracks, and repairing any cracked bulkhead. This NPRM also proposed to require reporting certain inspection results to M7 Aerospace LLC. We are issuing this AD to correct the unsafe condition on these products.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (78 FR 77618, December 24, 2013) or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (78 FR 77618, December 24, 2013) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (78 FR 77618, December 24, 2013).

Costs of Compliance

We estimate that this AD affects 360 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect visually F.S. 69.31 or F.S. 51.31 bulkhead (as applicable), looking for cracking in the radius.	12 work-hours × \$85 per hour = \$1,020 per inspection.	Not Applicable	\$1,020	\$367,200 per inspection cycle.

We estimate the following costs to do any necessary repairs that would be

required based on the results of the inspection. We have no way of

determining the number of airplanes that might need these repairs:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Repair damage	400 work-hours × \$85 per hour = \$34,000	\$8,000	\$42,000

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork

Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120-0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document

and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800

Independence Ave., SW., Washington, DC 20591. ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-06-01 M7 Aerospace LLC:

Amendment 39-17805, Docket No. FAA-2013-1057; Directorate Identifier 2013-CE-041-AD.

(a) Effective Date

This AD is effective April 25, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to M7 Aerospace LLC Models SA226-AT, SA226-T, SA226-T(B), SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, SA227-DC (C-26B), SA227-TT, SA26-AT, and SA26-T airplanes, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code: 5312, Fuselage Main, Bulkhead.

(e) Unsafe Condition

This AD was prompted by reports of airplanes with multiple fatigue cracks in the FS 69.31 front pressure bulkhead. We are issuing this AD to detect and correct cracks in the FS 51.31 (SA26 airplanes) and FS 69.31 (SA226 and SA227 airplanes) front pressure bulkhead, which if not corrected, could result in cabin depressurization.

(f) Compliance

Comply with this AD within the compliance times specified in paragraphs (h) through (j) of this AD, including all subparagraphs, unless already done.

(g) Inspection for Crack Damage

Do a detailed visual inspection of the front pressure bulkhead using the compliance times in paragraphs (h)(1) and (h)(2) of this AD, including all subparagraphs, as applicable.

(1) For all SA26-AT and SA26-T airplanes: Do a detailed visual inspection of the F.S. 51.31 front pressure bulkhead following paragraphs A. through E. of the Accomplishment Instructions in M7 Aerospace LLC SA26 Series Service Bulletin 26-53-001 R1, revised November 6, 2013.

(2) For all SA226-AT, SA226-T, SA226 T(B), and SA226-TC airplanes: Do a detailed visual inspection of the F.S. 69.31 front pressure bulkhead following paragraphs A. through E. of the Accomplishment Instructions in M7 Aerospace LLC SA226 Series Service Bulletin 226-53-017 R1, revised November 6, 2013.

(3) For all SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), and SA227-TT airplanes: Do a detailed visual inspection of the F.S. 69.31 front pressure bulkhead following paragraphs A. through E. of the Accomplishment Instructions in M7 Aerospace LLC SA227 Series Service Bulletin 227-53-011 R1, revised November 6, 2013.

(4) For all SA227-CC and SA227-DC (C-26B) airplanes: Do a detailed visual inspection of the F.S. 69.31 front pressure bulkhead following paragraphs A. through E. of the Accomplishment Instructions in M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-007 R1, revised November 6, 2013.

Note 1 to paragraph (g) of this AD:

Operators who had the initial inspection and resulting repairs accomplished using procedures different from the M7 Aerospace LLC service information required by this AD action may apply for an alternative method of compliance (AMOC) following the instructions in paragraph (m) of this AD.

(h) Bulkhead Inspection Compliance Times

(1) Initially do the inspections for crack damage required by paragraph (g)(1), (g)(2), (g)(3), or (g)(4) of this AD, as applicable, using the compliance times specified below:

(i) For airplanes with 30,000 or more hours TIS, perform the inspection within the next 150 hours TIS after April 25, 2014 (the effective date of this AD);

(ii) For airplanes with at least 25,000 but less than 30,000 hours TIS, perform the inspection within the next 300 hours TIS after April 25, 2014 (the effective date of this AD);

(iii) For airplanes with at least 20,000 but less than 25,000 hours TIS, perform the inspection within the next 450 hours TIS after April 25, 2014 (the effective date of this AD);

(iv) For airplanes with at least 11,000 but less than 20,000 hours TIS, perform the inspection within the next 600 hours TIS after April 25, 2014 (the effective date of this AD); or

(v) For airplanes with less than 11,000 hours TIS, perform the inspection before or upon accumulating 11,000 hours TIS or within the next 600 hours TIS after April 25, 2014 (the effective date of this AD), whichever occurs later.

(2) After the initial inspection specified in paragraph (h)(1) of this AD, to include all subparagraphs, repetitively thereafter do the inspections required in paragraph (g)(1), (g)(2), (g)(3), or (g)(4) of this AD, as applicable, at intervals not to exceed 1,000 hours TIS.

(i) Reporting Requirement for All Airplanes

If any cracks or other damage is found during any inspection required by paragraph (g)(1), (g)(2), (g)(3), or (g)(4) of this AD, before further flight, report all damage to M7 Aerospace LLC using the contact information and reporting criteria specified in paragraph F. of the Accomplishment Instructions in the service information listed in paragraphs (i)(1) through (i)(4) of this AD, as applicable:

(1) M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-007 R1, revised November 6, 2013.

(2) M7 Aerospace LLC SA227 Series Service Bulletin 227-53-011 R1, revised November 6, 2013.

(3) M7 Aerospace LLC SA26 Series Service Bulletin 26-53-001 R1, revised November 6, 2013.

(4) M7 Aerospace LLC SA226 Series Service Bulletin 226-53-017 R1, revised November 6, 2013.

(j) Repair of Crack Damage

If any damage is found during any inspection required by paragraph (g)(1), (g)(2), (g)(3), or (g)(4) of this AD, before further flight, repair the damage following paragraph G. of the Accomplishment Instructions in the service information listed in paragraphs (j)(1) through (j)(4) of this AD, as applicable. The repair scheme provided will be based on the damage reports submitted per paragraph (i) of this AD.

(1) M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-007 R1, revised November 6, 2013.

(2) M7 Aerospace LLC SA227 Series Service Bulletin 227-53-011 R1, revised November 6, 2013.

(3) M7 Aerospace LLC SA26 Series Service Bulletin 26-53-001 R1, revised November 6, 2013.

(4) M7 Aerospace LLC SA226 Series Service Bulletin 226-53-017 R1, revised November 6, 2013.

(k) Credit for Actions Accomplished in Accordance With Previous Service Information

This AD allows credit for the initial inspection and any resulting actions required in paragraphs (g)(1) through (g)(4), (i), and (j) of this AD, including all subparagraphs, if done before April 25, 2014 (the effective date of this AD), following the procedures specified in the Accomplishment Instructions of the applicable service information listed in paragraphs (k)(1) through (k)(4) of this AD:

(1) M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-007, dated September 26, 2013.

(2) M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin 227-53-011, dated September 26, 2013.

(3) M7 Aerospace LLC SA26 Series Service Bulletin 226-53-001, dated September 26, 2013.

(4) M7 Aerospace LLC SA226 Series Service Bulletin 226-53-017, dated September 26, 2013.

(l) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Fort Worth Airplane Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (n)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(n) Related Information

For more information about this AD, contact Andrew McAnaul, Aerospace Engineer, FAA, ASW-150 (c/o San Antonio MIDO), 10100 Reunion Place, Suite 650, San Antonio, Texas 78216; phone: (210) 308-3365; fax: (210) 308-3370; email: andrew.mcanaul@faa.gov.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-007 R1, revised November 6, 2013.

(ii) M7 Aerospace LLC SA227 Series Service Bulletin 227-53-011 R1, revised November 6, 2013.

(iii) M7 Aerospace LLC SA26 Series Service Bulletin 26-53-001 R1, revised November 6, 2013.

(iv) M7 Aerospace LLC SA226 Series Service Bulletin 226-53-017 R1, revised November 6, 2013.

(3) For M7 Aerospace LLC service information identified in this AD, contact M7 Aerospace LP, 10823 NE Entrance Road, San Antonio, Texas 78216; phone: (210) 824-9421; fax: (210) 804-7766; Internet: <http://www.elbitsystems-us.com>; email: none.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call 816-329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 7, 2014.

Steven W. Thompson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-05613 Filed 3-20-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2012-1318; Directorate Identifier 2012-NM-104-AD; Amendment 39-17789; AD 2014-05-16]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-200B, 747-300, 747-400, 747-400D, 747-400F series airplanes, and Model 767 series airplanes, powered by General Electric (GE) CF6-80C2 engines. This AD was prompted by reports of failure of the electro mechanical brake flexshaft (short flexshaft) of the thrust reverser actuation system (TRAS). This AD requires replacing the short flexshaft on each engine with a new short flexshaft, testing of the electro mechanical brake and center drive unit (CDU) cone brake to verify the holding torque, and performing related investigative and corrective actions if necessary. We are issuing this AD to prevent an uncommanded in-flight thrust reverser deployment and consequent loss of control of the airplane.

DATES: This AD is effective April 25, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of April 25, 2014.

ADDRESSES: For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

For Middle River Aircraft Systems service information identified in this AD, contact Middle River Aircraft Systems, 103 Chesapeake Park Plaza, Baltimore, MD 21220; telephone 410-682-1500; fax 410-682-1230; email info@mras-usa.com; Internet <http://www.mras-usa.com/contact.html>.

You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.