

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2014-0451; Directorate Identifier 2013-NM-122-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88 airplanes. This proposed AD was prompted by reports of cracks emanating from the aft-most barrel nut holes of the left and right upper rear spar caps of the horizontal stabilizer. This proposed AD would require repetitive high frequency eddy current (ETHF) inspections for cracks in the areas around the two aft-most barrel nut holes of the upper rear spar caps, and corrective actions if necessary; and repetitive ETHF inspections for cracks in the areas around the two aft-most barrel nut holes of any repaired or replaced upper rear spar cap, and corrective actions if necessary. We are proposing this AD to detect and correct cracks in the horizontal stabilizer, which could propagate until an upper rear spar cap severs, and result in failure of the horizontal stabilizer upper center or aft skin panel and adversely affect the structural integrity of the airplane.

DATES: We must receive comments on this proposed AD by September 2, 2014.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing

Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425 227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

George Garrido, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5357; fax: 562-627-5210; email: george.garrido@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0451; Directorate Identifier 2013-NM-122-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports of cracks emanating from the aft-most barrel nut

holes of the left and right upper rear spar caps of the horizontal stabilizer. One airplane had accumulated 40,144 total flight hours and 32,253 total landing cycles, while another airplane had accumulated 58,296 total flight hours and 43,512 total landing cycles. Investigations have determined that the cracks were caused by fatigue. In both cases, the cracks originated inside of the barrel nut holes, and radiated vertically and in the aft direction from the barrel nut holes. This condition, if not corrected, could result in cracks in the horizontal stabilizer, which could propagate until an upper rear spar cap severs, and result in failure of the horizontal stabilizer upper center or aft skin panel and adversely affect the structural integrity of the airplane.

Relevant Service Information

We reviewed Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013. For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0451.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require repetitive ETHF inspections for cracks in the areas around the two aft-most barrel nut holes of the left and right upper rear spar caps, and corrective actions if necessary; and repetitive ETHF inspections for cracks in the areas around the two aft-most barrel nut holes of any the repaired or replaced upper rear spar cap, and corrective actions if necessary.

The phrase "corrective actions" is used in this proposed AD. "Corrective actions" are actions that correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

Costs of Compliance

We estimate that this proposed AD affects 668 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	5 work-hours × \$85 per hour = \$425 per inspection cycle.	\$0	\$425 per inspection cycle.	\$283,900 per inspection cycle.

We estimate the following costs to do any necessary repairs and replacements that would be required based on the

results of the proposed inspection. We have no way of determining the number

of aircraft that might need these repairs and replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Repair	Up to 394 work-hours × \$85 per hour = \$33,490	Up to \$32,440	Up to \$65,930.
Replacement	Up to 394 work-hours × \$85 per hour = \$33,490	Up to \$60,222	Up to \$93,712.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2014–0451; Directorate Identifier 2013–NM–122–AD.

(a) Comments Due Date

We must receive comments by September 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model DC–9–81 (MD–81), DC–9–82 (MD–82), DC–9–83 (MD–83), DC–9–87 (MD–87), and MD–88 airplanes; certificated in any category.

(d) Subject

Air Transport Association (ATA) Code 55, Stabilizers.

(e) Unsafe Condition

This AD was prompted by reports of cracks emanating from the aft-most barrel nut holes of the left and right upper rear spar caps of the horizontal stabilizer. We are issuing this AD to detect and correct cracks in the horizontal stabilizer, which could propagate until an upper rear spar cap severs, and result in failure of the horizontal stabilizer upper center or aft skin panel and adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

At the applicable compliance time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013; except as provided by paragraph (i) of this AD: Do a high frequency eddy current inspection (ETHF) for cracks in the areas around the two aft-most barrel nut holes of the left and right upper rear spar caps, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013. Thereafter, repeat the ETHF inspection at the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013; except as provided by paragraph (i) of this AD. If any cracking is found during any inspection, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013.

(h) Post-Repair/Replacement Actions

For airplanes on which a splice repair or replacement was done, as specified in Boeing Alert Service Bulletin MD80–55A070: At the applicable compliance time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013, do a ETHF inspection for cracks at the two aft-most barrel nut holes of any repaired or replaced upper rear spar cap, in accordance

with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013. Thereafter, repeat the ETHF inspection at the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013. If any cracking is found during any inspection, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013.

(i) Exception to the Service Information Specifications

Where Boeing Alert Service Bulletin MD80–55A070, Revision 1, dated December 17, 2013, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin MD80–55A070, dated May 22, 2013, which is not incorporated by reference in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and 14 CFR 25.571, Amendment 45, and the approval must specifically refer to this AD.

(l) Related Information

(1) For more information about this AD, contact George Garrido, Aerospace Engineer, Airframe Branch, ANM–120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5357; fax: 562–627–5210; email: george.garrido@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800–0019, Long Beach, CA 90846–0001;

telephone 206–544–5000, extension 2; fax 206–766–5683; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 11, 2014.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014–16940 Filed 7–17–14; 8:45 am]

BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA–R07–OAR–2014–0400; FRL–9913–80–Region–7]

Approval and Promulgation of Implementation Plans; State of Missouri, Auto Exhaust Emission Controls

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing to take direct final action to approve the State Implementation Plan (SIP) revision submitted by the state of Missouri on January 14, 2014, for the purpose of removing an outdated rule. This action amends the SIP to remove a rule that was originally approved in 1972 but has now been rescinded. This rule refers to exhaust emission control components that are no longer manufactured. Vehicle manufacturers now produce newer technology in exhaust emissions equipment in order to meet more stringent Federal motor vehicle standards.

DATES: Comments on this proposed action must be received in writing by August 18, 2014.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA–R07–OAR–2014–0400, by mail to Paula Higbee, Environmental Protection Agency, Air Planning and Development Branch, 11201 Renner Boulevard, Lenexa, Kansas 66219. Comments may also be submitted electronically or through hand delivery/courier by following the detailed instructions in the **ADDRESSES** section of the direct final rule located in the rules section of this **Federal Register**.

FOR FURTHER INFORMATION CONTACT: Paula Higbee, Environmental Protection

Agency, Air Planning and Development Branch, 11201 Renner Boulevard, Lenexa, Kansas 66219 at 913–551–7028, or by email at higbee.paula@epa.gov.

SUPPLEMENTARY INFORMATION: In the final rules section of the **Federal Register**, EPA is approving the state’s SIP revision as a direct final rule without prior proposal because the Agency views this as a noncontroversial revision amendment and anticipates no relevant adverse comments to this action. A detailed rationale for the approval is set forth in the direct final rule. If no relevant adverse comments are received in response to this action, no further activity is contemplated in relation to this action. If EPA receives relevant adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed action. EPA will not institute a second comment period on this action. Any parties interested in commenting on this action should do so at this time. Please note that if EPA receives adverse comment on part of this rule and if that part can be severed from the remainder of the rule, EPA may adopt as final those parts of the rule that are not the subject of an adverse comment. For additional information, see the direct final rule which is located in the rules section of this **Federal Register**.

Dated: July 1, 2014.

Karl Brooks,

Regional Administrator, Region 7.

[FR Doc. 2014–16701 Filed 7–17–14; 8:45 am]

BILLING CODE 6560–50–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA–R06–OAR–2013–0764; FRL–9913–93–Region 6]

Approval and Promulgation of Air Quality Implementation Plans; New Mexico; Grant County Sulfur Dioxide Limited Maintenance Plan

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing to approve a limited maintenance plan submitted by the State of New Mexico, dated November 1, 2013, for the Grant County maintenance area for the 1971 sulfur dioxide (SO₂) National Ambient Air Quality Standard (NAAQS). New Mexico submitted this limited