

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (n)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2017-0161R1, dated September 19, 2017; corrected September 20, 2017; for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0077.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW, Renton, Washington 98057-3356; telephone 425-227-1405; fax 425-227-1149.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW, Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on February 2, 2018.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018-02754 Filed 2-9-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2017-1050; Product Identifier 2017-NE-39-AD]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG Turbofan Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Rolls-Royce Deutschland Ltd & Co KG (RRD) BR700-710A2-20 and BR700-710C4-11 turbofan engines. This proposed AD was prompted by reports of deterioration of the intumescent heat resistant paint system on the electronic engine controller (EEC) firebox assembly that was found to be beyond acceptable limits. This proposed AD would require replacement of affected EEC firebox assembly parts with improved parts, which have a more durable paint system. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this NPRM by March 29, 2018.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, Dahlewitz, 15827 Blankenfelde-Mahlow, Germany; phone: +49 (0) 33 7086 2673; fax: +49 (0) 33 7086 3276.

You may view this service information at the FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7759.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1050; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Martin Adler, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7157; fax: 781-238-7199; email: [martin.adler@faa.gov](mailto:martin.adler@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2017-1050; Product Identifier 2017-NE-39-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2017-0198, dated October 10, 2017 (referred to hereinafter as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Occurrences were reported where deterioration of an Electronic Engine Controller (EEC) firebox assembly

intumescent heat resistant paint system was found to be beyond acceptable limits. Subsequent investigation determined that lack of paint adhesion, due to incorrect surface preparation during manufacturing, had caused this deterioration.

This condition, if not corrected, could reduce the fire protection capability of the EEC firebox, possibly leading to reduced control of an engine during engine fire, engine overspeed and release of high-energy debris, resulting in damage to, and/or reduced control of, the aeroplane.

To address this potential unsafe condition, RRD issued Alert SB SB-BR700-73-A101977, SB-BR700-73-A101981 and SB-BR700-73-A101985 to provide modification instructions introducing improved new or reworked EEC firebox assembly parts, which have a more durable paint system.

For the reason described above, this AD requires replacement of affected EEC firebox assembly parts with improved parts.

You may obtain further information by examining the MCAI in the AD

docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1050.

**Related Service Information**

We reviewed RRD Alert Service Bulletin (ASB) SB-BR700-73-A101977, Revision 3, dated July 10, 2017; RRD ASB SB-BR700-73-A101981, Revision 3, dated July 10, 2017; and RRD ASB SB-BR700-73-A101985, Revision 3, dated July 10, 2017. The service information describes procedures for installing new or reworked EEC firebox assembly parts for BR700-710A2-20, BR700-710C4-11, and BR700-710C4-11/10 engines, respectively.

**FAA’s Determination**

This product has been approved by the aviation authority of Germany, and is approved for operation in the United States. Pursuant to our bilateral

agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements**

This proposed AD would require replacement of affected EEC firebox assembly parts with improved parts, which have a more durable paint system.

**Costs of Compliance**

We estimate that this proposed AD affects 842 engines installed on airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
EEC firebox assembly replacement .....	2.5 work-hours × \$85 per hour = \$212.50.	\$4,900	\$5,112.50	\$4,304,725

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and

associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Rolls-Royce Deutschland GmbH (Type Certificate previously held by Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH):** Docket No. FAA-2017-1050; Product Identifier 2017-NE-39-AD.

**(a) Comments Due Date**

We must receive comments by March 29, 2018.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to: (1) Rolls-Royce Deutschland (RRD) BR700-710A2-20 turbofan engines with any of the following electronic engine controller (EEC) firebox assembly part numbers (P/Ns)

installed: FW42888, FW42886, FW38590, FW38591, or FW58255.

(2) RRD BR700-710C4-11 turbofan engines with any of the following EEC firebox assembly P/Ns installed: FW38504, FW38503, FW38590, FW38591, or FW58255.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7600, Engine Controls.

**(e) Unsafe Condition**

This AD was prompted by reports of deterioration of the intumescent heat resistant paint system on the EEC firebox assembly that was found to be beyond acceptable limits. We are issuing this AD to prevent failure of the EEC. The unsafe condition, if not corrected, could result in failure of the EEC, loss of engine thrust control, and reduced control of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) Within 6 months after the effective date of this AD, perform the following:

(i) For RRD BR700-710A2-20 engines, remove from service the EEC firebox assembly components with P/N FW42888, FW42886, FW38590, FW38591, and FW58255 and replace with parts eligible for installation.

(ii) For RRD BR700-710C4-11 engines, remove from service the EEC firebox assembly components with P/N FW38504, FW38503, FW38590, FW38591, and FW58255 and replace with parts eligible for installation.

(2) Reserved.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: [ANE-AD-AMOC@faa.gov](mailto:ANE-AD-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

(1) For more information about this AD, contact Martin Adler, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7157; fax: 781-238-7199; email: [martin.adler@faa.gov](mailto:martin.adler@faa.gov).

(2) Refer to MCAI EASA AD No. 2017-0198, dated October 10, 2017, for more information. You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2017-1050.

Issued in Burlington, Massachusetts, on February 5, 2018.

**Robert J. Ganley,**

*Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.*

[FR Doc. 2018-02600 Filed 2-9-18; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

**[Docket No. FAA-2017-0783; Airspace Docket No. 17-AEA-13]**

**Proposed Revocation of Class E Airspace; Seven Springs, PA, and Somerset, PA**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to remove Class E airspace at Seven Springs, PA, as Seven Springs Borough Airport has been abandoned, and controlled airspace is no longer required. This proposal would also remove reference to the Seven Springs, PA, Class E airspace area from the Somerset County Airport, Somerset, PA, description, and update the geographic coordinates of Somerset County Airport to coincide with the FAA's database. This action would enhance the safety and management of controlled airspace within the national airspace system.

**DATES:** Comments must be received on or before March 29, 2018.

**ADDRESSES:** Send comments on this rule to: U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12-140, Washington, DC 20590-0001; Telephone: (800) 647-5527, or (202) 366-9826. You must identify the Docket No. FAA-2017-0783; Airspace Docket No. 17-AEA-13, at the beginning of your comments. You may also submit comments through the internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence

Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11B at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Ave., College Park, GA 30337; telephone (404) 305-6364.

**SUPPLEMENTARY INFORMATION:**

**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would remove Class E airspace extending upward from 700 feet above the surface at Seven Springs Borough Airport, Seven Springs, PA, due to the closing of the airport.

**Comments Invited**

Interested persons are invited to comment on this rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2017-0783 and Airspace Docket No. 17-AEA-13) and be submitted in triplicate to the DOT Docket Operations (see **ADDRESSES** section for address and phone number). You may also submit comments through the internet at <http://www.regulations.gov>.