

**Authority:** 12 U.S.C. 1757, 1766, and 1781-1790. Section 741.11 is also authorized by 31 U.S.C. 3717.

3. Section 741.3 is amended by revising the heading and adding new paragraph (c) to read as follows:

**§ 741.3 Other requirements.**

\* \* \* \* \*

(c) Adhere to the requirements stated in Part 703 of this chapter concerning transacting business with corporate credit unions.

[FR Doc. 95-10149 Filed 4-25-95; 8:45 am]

BILLING CODE 7535-01-P

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. 94-NM-110-AD]

**Airworthiness Directives; British Aerospace Model Viscount 744, 745D, and 810 Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all British Aerospace Model Viscount 744, 745D, and 810 series airplanes. This proposal would require repetitive inspections to detect discrepancies of certain fittings and the actuator beam structure of the nose landing gear, and replacement of discrepant parts. This proposal is prompted by reports of fatigue cracking of the undercarriage bracing of the nose wheel. The actions specified by the proposed AD are intended to prevent such fatigue cracking, which could result in the failure of the structure and fittings, and subsequent collapse of the nose landing gear.

**DATES:** Comments must be received by May 5, 1995.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-110-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from British Aerospace Regional Aircraft Ltd.,

Engineering Support Manager, Military Business Unit, Chadderton Works, Greengate, Middleton, Manchester M24 1SA, England. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:**

William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1320.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-NM-110-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-110-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

**Discussion**

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on all British Aerospace Model Viscount 744, 745D, and 810 airplanes.

The CAA advises that reports have been received of cracking in the bracing structures of the nose wheel undercarriage on these airplanes. Investigation revealed that the cracking was fatigue related, and that deterioration of the structure also has occurred. These conditions, if not detected and corrected in a timely manner, could result in the collapse of the nose landing gear.

British Aerospace has issued Viscount Alert Preliminary Technical Leaflet (PTL) 331, VIS 1 Doc 12 (for Model 744 and 745D airplanes), and PTL 202, VIS 1 Doc. 4 (for Model 810 airplanes), both dated November 1, 1991. These PTL's describe the following procedures:

1. Procedures for repetitive non-destructive testing (NDT) inspections to detect cracking of the actuator attachment fittings of the nose landing gear.

2. Procedures for repetitive visual inspections to detect signs of structural deterioration of the central diaphragms of the actuator beam structure.

3. Procedures to detect elongation, cracking, buckling in the central diaphragms and reinforcing angles, and loosening of fasteners of the mounting bolt holes of the actuator attachment. And

4. Procedures for replacement of deteriorated or cracked parts with new parts. The CAA classified these alert PTL's as mandatory in order to assure the continued airworthiness of these airplanes in the United Kingdom.

This airplane model is manufactured in the United Kingdom and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require repetitive inspections to detect discrepancies of certain fittings and the actuator beam structure of the nose landing gear, and replacement of discrepant parts. The actions would be required to be accomplished in accordance with the alert PTL's described previously.

As a result of recent communications with the Air Transport Association (ATA) of America, the FAA has learned that, in general, some operators may misunderstand the legal effect of AD's on airplanes that are identified in the applicability provision of the AD, but that have been altered or repaired in the area addressed by the AD. The FAA points out that all airplanes identified in the applicability provision of an AD are legally subject to the AD. If an airplane has been altered or repaired in the affected area in such a way as to affect compliance with the AD, the owner or operator is required to obtain FAA approval for an alternative method of compliance with the AD, in accordance with the paragraph of each AD that provides for such approvals. A note has been included in this notice to clarify this long-standing requirement.

The FAA estimates that 29 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 15 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$26,100, or \$900 per airplane, per inspection cycle.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the

location provided under the caption ADDRESSES.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**British Aerospace Regional Aircraft Limited (Formerly British Aerospace Commercial Aircraft Limited, Vickers-Armstrongs Aircraft Limited):** Docket 94-NM-110-AD.

*Applicability:* All Model Viscount 744, 745D, and 810 airplanes, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent collapse of the nose landing gear, accomplish the following:

(a) Prior to the accumulation of 2,050 landings after the effective date of this AD, or within 12 months after the effective date of this AD, whichever occurs first: Perform a visual inspection and non-destructive testing (NDT) inspection to detect discrepancies of the actuator beam structure and actuator attachment fittings of the nose landing gear, in accordance with Viscount Alert Preliminary Technical Leaflet (PTL) 331 VIS 1 Doc 12 (for Model 744 and 745D airplanes), or PTL 202, VIS 1 Doc. 4 (for Model Viscount

810 airplanes), both dated November 1, 1991, as applicable. Thereafter, repeat these inspections at intervals not to exceed 2,050 landings.

(b) If any discrepancy is found, prior to further flight, replace the discrepant part with a new part, in accordance with Viscount Alert PTL 331, VIS 1 Doc 12 (for Model 744 and 745D airplanes), or PTL 202, VIS 1 Doc. 4 (for Model 810 airplanes), both dated November 1, 1991, as applicable.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 20, 1995.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 95-10199 Filed 4-25-95; 8:45 am]

BILLING CODE 4910-13-U

#### 14 CFR Part 39

[Docket No. 95-NM-27-AD]

#### Airworthiness Directives; British Aerospace Model BAe 146-100A, -200A, and -300A Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain British Aerospace Model BAe 146-100A, -200A, and -300A airplanes. This proposal would require modification of the elevator control system of the flight controls. This proposal is prompted by reports of low frequency constant amplitude oscillations of the elevator control system and non-centering of the pitch control upon autopilot disconnect. The actions specified by the proposed AD are intended to prevent uncommanded descent upon autopilot disconnect and reduced controllability of the airplane