

national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ Section 39.13 [AMENDED]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

95-24-11 Fairchild Aircraft: Amendment 39-9441; Docket No. 95-CE-01-AD.

Applicability: The following airplane models and serial numbers, certificated in any category:

Model	Serial Nos.
SA226-T	All serial numbers.
SA226-T(B) ...	All serial numbers.
SA226-AT	All serial numbers.
SA226-TC	All serial numbers.
SA227-AT	All serial numbers.
SA227-AC	All serial numbers.
SA227-BC	All serial numbers.
SA227-TT	All serial numbers.

Model	Serial Nos.
SA227-CC	CC784 and CC790 through CC863
SA227-DC	DC784 and DC790 through DC863

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it. Compliance: Required within the next 600 hours time-in-service after the effective date of this AD, unless already accomplished.

To prevent airplane flight control jammings caused by objects falling through the cockpit floor openings, accomplish the following:

(a) Install foreign object damage (FOD) barriers in the floorboards of the cockpit between the pedestal and floor from Fuselage Station (FS) 79.38 to FS 88.06 and on the outboard forward edge of the left-hand and right-hand cockpit forward floorboards at FS 79.38. Accomplish this action in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of either Fairchild Service Bulletin (SB) 226-53-012, Fairchild SB 227-53-005, or Fairchild SB CC7-53-002, all Issued: September 22, 1994, as applicable.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Airplane Certification Office (ACO), FAA, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Fort Worth ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Fort Worth ACO.

(d) The installation required by this AD shall be done in accordance with Fairchild Service Bulletin 226-53-012, Fairchild Service Bulletin 227-53-005, or Fairchild Service Bulletin CC7-53-002, all Issued: September 22, 1994. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fairchild Aircraft, P.O. Box 790490, San Antonio, Texas 78279-0490. Copies may be inspected at the FAA, Central

Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., 7th Floor, suite 700, Washington, DC.

(e) This amendment (39-9441) becomes effective on January 3, 1996.

Issued in Kansas City, Missouri, on November 17, 1995.

Michael Gallagher,
Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-28794 Filed 11-24-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-83-AD; Amendment 39-9434; AD 95-24-02]

Airworthiness Directives; Boeing Model 747SP Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747SP series airplanes, that requires modification of the escape slide/raft on Door 2 of the airplane. This amendment is prompted by reports indicating that the escape slide/raft on Door 2 deployed onto the wing of the airplane and did not inflate automatically. The actions specified by this AD are intended to ensure that the escape slide/raft on Door 2 inflates automatically so that passengers are able to exit the airplane through Door 2 in the event of an emergency evacuation.

DATES: Effective December 27, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 27, 1995.

ADDRESSES: The service information referenced in this AD may be obtained from BFGoodrich Company, Aircraft Evacuation Systems, Department 7916, Phoenix, Arizona 85040. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Monica Nemecek, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2773; fax (206) 227-1181.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 747SP series airplanes was published in the Federal Register on August 10, 1995 (60 FR 40783). That action proposed to require modification of the escape slide/raft on Door 2 of the airplane.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

There are approximately 45 Model 747SP series airplanes of the affected design in the worldwide fleet. The FAA estimates that 12 airplanes of U.S. registry will be affected by this AD, that it will take approximately 2 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$259 per airplane. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$4,548, or \$379 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is

contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-24-02 Boeing: Amendment 39-9434.
Docket 95-NM-83-AD.

Applicability: Model 747SP series airplanes equipped with BFGoodrich evacuation systems identified in BFGoodrich Service Bulletin 7A1255-25-275, dated February 25, 1994, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To ensure the ability of passengers to exit the airplane through Door 2 in the event of an emergency evacuation, accomplish the following:

(a) Within 36 months after the effective date of this AD, modify the escape slide/raft on Door 2 in accordance with BFGoodrich Service Bulletin 7A1255-25-275, dated February 25, 1994.

(b) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The modification shall be done in accordance with BFGoodrich Service Bulletin 7A1255-25-275, dated February 25, 1994. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from BFGoodrich Company, Aircraft Evacuation Systems, Department 7916, Phoenix, Arizona 85040. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on December 27, 1995.

Issued in Renton, Washington, on November 9, 1995.

S.R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-28795 Filed 11-24-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-49-AD; Amendment 39-9435; AD 95-24-03]

Airworthiness Directives; McDonnell Douglas Model DC-10-10, -30, and -40 Series Airplanes, and KC-10 (Military) Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-10, -30, and -40 series airplanes, and KC-10 (military) airplanes, that requires inspections to detect corrosion or cracking of the lower front spar cap and the skin panel of the horizontal stabilizer, and repair of corroded or cracked parts. This amendment also requires eventual modification of the horizontal stabilizer, which terminates the inspection requirements. This action is prompted by reports indicating that corrosion,