

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency AD No.: 2007-0027, dated February 5, 2007, for related information.

Material Incorporated by Reference

(i) You must use Vulcanair S.p.A. Service Bulletin No. 120 Rev. 1, dated June 7, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Vulcanair S.p.A, Via G. Pascoli, 7, Casoria (Naples), 80026 Italy; telephone: +39 081 5918111; fax: +39 081 5918172; e-mail: info@vulcanair.com; Internet: <http://www.vulcanair.com>.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on November 19, 2008.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-27916 Filed 11-26-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0835; Directorate Identifier 2008-SW-34-AD; Amendment 39-15684; AD 2008-20-05]

RIN 2120-AA64

Airworthiness Directives; MD Helicopters, Inc. Model 600N Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects airworthiness directive (AD) 2008-20-05 which was published on October 10, 2008 (73 FR 60102) and applies to MD Helicopters, Inc. (MDHI) Model 600N helicopters. AD 2008-20-05 requires modifying the fuselage aft section,

repetitively inspecting the tailboom attachment fittings, installing inspection holes and attachment bolt washers, modifying both access covers, and replacing broken attachment bolts. This document corrects the AD number that is incorrectly listed as 2008-20-08 on page 60104 of the AD.

DATES: The effective date of AD 2008-20-05 remains October 27, 2008.

FOR FURTHER INFORMATION CONTACT: Eric Schrieber, Aviation Safety Engineer, FAA, Los Angeles Aircraft Certification Office, Airframe Branch, 3960 Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5348, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Discussion: On September 25, 2008, we issued AD 2008-20-05 to amend 14 CFR part 39 to include an AD that applies to MDHI Model 600N helicopters. That AD requires modifying the fuselage aft section, repetitively inspecting the tailboom attachment fittings, installing inspection holes and attachment bolt washers, modifying both access covers, and replacing broken attachment bolts.

As published, AD 2008-20-05 contains an incorrect AD number (2008-20-08) in the regulatory text on page 60104 of the AD. The correct AD number is 2008-20-05.

No other part of the regulatory information has been changed; therefore, the AD is not republished in the **Federal Register**.

Correction of Publication

Accordingly, the publication on October 10, 2008 of Amendment 39-15684, AD 2008-20-05, Docket No. FAA-2008-0835, Directorate Identifier 2008-SW-34-AD (73 FR 60102), which is the subject of FR Doc. E8-23540, is corrected as follows:

§ 39.13 [Corrected]

On page 60104, in the second column, in the paragraph under § 39.13 [Amended], change "2008-20-08" to read "2008-20-05".

Issued in Fort Worth, Texas, on November 14, 2008.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. E8-28108 Filed 11-26-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1238; Directorate Identifier 2008-NM-181-AD; Amendment 39-15753; AD 2008-24-12]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model BD-700-1A10 and BD-700-1A11 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During scheduled maintenance inspection, a bolt which connects the PCU (power control unit) to the elevator surface was found fractured in the assembly. Further inspection of the assembly revealed that the bearing on the PCU rod end had seized, which resulted in damage to the attachment fitting bushing and fracture of the bolt. Inspection of other in-service airplanes revealed two more seized PCU attachment joints. However, except seizure, no fractured bolt was found on these airplanes. Failure of the bolts in both PCUs on one side could result in disconnection of the elevator control surface which would lead to flutter and loss of the aircraft.

* * * * *

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective December 15, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of December 15, 2008.

We must receive comments on this AD by December 29, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

• **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Pong K. Lee, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart

Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7324; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, has issued Canadian Emergency Airworthiness Directive CF-2008-31, dated October 9, 2008 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

During scheduled maintenance inspection, a bolt which connects the PCU (power control unit) to the elevator surface was found fractured in the assembly. Further inspection of the assembly revealed that the bearing on the PCU rod end had seized, which resulted in damage to the attachment fitting bushing and fracture of the bolt. Inspection of other in-service airplanes revealed two more seized PCU attachment joints. However, except seizure, no fractured bolt was found on these airplanes. Failure of the bolts in both PCUs on one side could result in disconnection of the elevator control

surface which would lead to flutter and loss of the aircraft.

This Airworthiness Directive (AD) is issued to mandate the inspection and lubrication of all part number (P/N) GT411-3800-5 and GT411-3800-7 PCU attachment joints.

The required actions include inspections for damage and seizure (including signs of seizure) of the PCU attachment joints, an inspection for damage (including wear damage, fretting, corrosion, galling, scoring, fretting wear, and parts that do not meet inspection requirements) of the PCU attachment joint components, and applicable corrective actions. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Bombardier has issued the service information in the following table. The actions described in the service information are intended to correct the unsafe condition identified in the MCAI.

SERVICE BULLETINS

Service Bulletin	Revision level	Date
Bombardier Alert Service Bulletin A700-1A11-27-024	01	October 3, 2008.
Bombardier Alert Service Bulletin A700-27-066	01	October 3, 2008.
Bombardier Service Bulletin 700-1A11-27-025	Original	October 9, 2008.
Bombardier Service Bulletin 700-27-067	Original	October 9, 2008.

FAA’s Determination and Requirements of This AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between the AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

FAA’s Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because failure of the bolts in both PCUs on one side of the airplane could cause disconnection of the elevator control surface which could result in flutter and consequent loss of the airplane. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We

invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2008-1238; Directorate Identifier 2008-NM-181-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

2008-24-12 Bombardier: Amendment 39-15753. Docket No. FAA-2008-1238; Directorate Identifier 2008-NM-181-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective December 15, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Bombardier Model BD-700-1A10 and BD-700-1A11 airplanes, certificated in any category, serial numbers (S/Ns) 9002 through 9222 inclusive; equipped with elevator power control units (PCUs) having part number (P/N) GT411-3800-5 or GT411-3800-7.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight controls.

Reason

(e) The mandatory continued airworthiness information (MCAI) states:

During scheduled maintenance inspection, a bolt which connects the PCU (power control unit) to the elevator surface was found fractured in the assembly. Further inspection of the assembly revealed that the bearing on the PCU rod end had seized, which resulted in damage to the attachment fitting bushing and fracture of the bolt. Inspection of other in-service airplanes revealed two more seized PCU attachment joints. However, except seizure, no fractured bolt was found on these airplanes. Failure of the bolts in both PCUs on one side could result in disconnection of the elevator control surface which would lead to flutter and loss of the aircraft.

This Airworthiness Directive (AD) is issued to mandate the inspection and lubrication of all part number (P/N) GT411-3800-5 and GT411-3800-7 PCU attachment joints.

The required actions include inspections for damage and seizure (including signs of seizure) of the PCU attachment joints, an inspection for damage (including wear damage, fretting, corrosion, galling, scoring, fretting wear, and parts that do not meet inspection requirements) of the PCU attachment joint components, and applicable corrective actions.

Actions and Compliance

(f) Unless already done: For airplanes on which elevator PCUs with P/N GT411-3800-5 or P/N GT411-3800-7, S/N 0615 and lower, are installed, excluding P/N GT411-3800-7 PCUs having a serial number listed in Table 1 of this AD, and excluding P/N GT411-3800-7 PCUs on which less than 1,000 flight hours have accumulated on the PCUs as of the effective date of this AD, do the actions specified in paragraphs (f)(1), (f)(2), and (f)(3) of this AD.

Note 1: Units listed in Table 1 of this AD have been lubricated by the vendor and the inspections required by paragraphs (f)(1), (f)(2), (f)(3), and (f)(4) of this AD are not required for those units.

TABLE 1—SERIAL NUMBERS

0030	0097	0156	0188	0218	0369	0438
0031	0101	0161	0190	0222	0406	0453
0033	0105	0163	0191	0223	0407	0491
0041	0108	0164	0197	0240	0408	0495
0046	0109	0165	0198	0262	0413	0504
0060	0110	0171	0199	0265	0420	0506
0062	0111	0173	0202	0281	0427	0513
0066	0119	0174	0205	0296	0429	0533
0081	0130	0178	0206	0301	0430	0536
0083	0138	0179	0208	0310	0431	0586
0087	0141	0181	0210	0323	0433	
0092	0145	0183	0214	0365	0435	

(1) Within 10 flight cycles or 50 flight hours after the effective date of this AD, whichever occurs first: Inspect for damage and wear and lubricate the PCU attachment joints in accordance with Bombardier Alert Service Bulletin A700-1A11-27-024, Revision 01, dated October 3, 2008; or Bombardier Alert Service Bulletin A700-27-

066, Revision 01, dated October 3, 2008; as applicable.

(2) Within 90 days or 200 flight hours after performing the actions required by paragraph (f)(1) of this AD, whichever occurs first: Repeat the inspection and lubrication of the PCU attachment joints in accordance with Bombardier Alert Service Bulletin A700-

1A11-27-024, Revision 01, dated October 3, 2008; or Bombardier Alert Service Bulletin A700-27-066, Revision 01, dated October 3, 2008; as applicable.

(3) Within 45 days or 100 flight hours after performing the actions required by paragraph (f)(2) of this AD, whichever occurs first: Repeat the inspection and lubrication of the

PCU attachment joints in accordance with Bombardier Alert Service Bulletin A700-1A11-27-024, Revision 01, dated October 3, 2008; or Bombardier Alert Service Bulletin A700-27-066, Revision 01, dated October 3, 2008; as applicable. Repeat the inspection thereafter at intervals not to exceed 45 days or 100 flight hours, whichever occurs first, until paragraph (f)(4) of this AD is accomplished.

(4) Completion of a disassembly with an inspection for damage, applicable corrective actions, and lubrication of the PCU attachment joint components in accordance with Bombardier Service Bulletin 700-1A11-27-025, dated October 9, 2008; or Bombardier Service Bulletin 700-27-067,

dated October 9, 2008; as applicable; constitutes terminating action for the inspections required by paragraphs (f)(1), (f)(2), and (f)(3) of this AD.

(5) Unless already done, if any damage or seizure is found during any inspection required by paragraphs (f)(1), (f)(2), (f)(3), and (f)(4) of this AD, before further flight, replace the affected part in accordance with Bombardier Service Bulletin 700-1A11-27-025, dated October 9, 2008, or Bombardier Service Bulletin 700-27-067, dated October 9, 2008, as applicable.

(6) Actions done before the effective date of this AD in accordance with the Bombardier Alert Service Bulletins A700-1A11-27-024 and A700-27-066, both dated

October 2, 2008, are acceptable for compliance with the corresponding requirements of this AD.

(7) Unless already done, submit a report to Bombardier of all findings found during any inspection required by this AD, in accordance with the applicable service bulletin listed in Table 2 of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 14 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 14 days after the effective date of this AD.

TABLE 2—SERVICE BULLETINS FOR REPORTS

Service Bulletin	Revision level	Date
Bombardier Alert Service Bulletin; A700-1A11-27-024	01	October 3, 2008.
Bombardier Alert Service Bulletin; A700-27-066	01	October 3, 2008.
Bombardier Service Bulletin; 700-1A11-27-025	Original	October 9, 2008.
Bombardier Service Bulletin; 700-27-067	Original	October 9, 2008.

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows:

(1) This AD does not mandate the terminating action specified in paragraph A.4. of the MCAI; it is included as an optional terminating action in paragraph (f)(4) of this AD. The planned compliance times for that action would allow enough time to provide notice and opportunity for prior public comment on the merits of those actions. Therefore, we are considering further rulemaking to require the terminating action on all affected airplanes.

(2) Paragraph A.3. of the MCAI requires a one-time inspection; however, since we have changed the terminating action in paragraph A.4. of the MCAI to an optional action, paragraph (f)(3) of this AD requires repeating the inspections until the terminating action is performed.

(3) This AD does not require the inspection and lubrication of PCUs specified in Paragraph B. of the MCAI. The planned compliance times for those actions would allow enough time to provide notice and opportunity for prior public comment on the merits of those actions. Therefore, we are considering further rulemaking to address this issue.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft

Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Pong K. Lee, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7324; fax (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

(4) *Special Flight Permits:* As described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), special flight permits are not allowed.

Related Information

(h) Refer to Mandatory Continuing Airworthiness Information (MCAI) Transport Canada Civil Aviation Emergency Airworthiness Directive CF-2008-31, dated October 9, 2008, and the service information specified in Table 2 of this AD, for related information.

Material Incorporated by Reference

(i) You must use the service information specified in Table 3 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 3—MATERIAL INCORPORATED BY REFERENCE

Service Bulletin	Revision level	Date
Bombardier Alert Service Bulletin A700-1A11-27-024	01	October 3, 2008.
Bombardier Alert Service Bulletin A700-27-066	01	October 3, 2008.
Bombardier Service Bulletin 700-1A11-27-025	Original	October 9, 2008.
Bombardier Service Bulletin 700-27-067	Original	October 9, 2008.

Issued in Renton, Washington, on November 16, 2008.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-28103 Filed 11-26-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0176; Directorate Identifier 2007-NM-228-AD; Amendment 39-15748; AD 2008-24-08]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, -800 and -900 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Boeing Model 737-600, -700, -700C, -800 and -900 series airplanes. This AD requires an inspection of the escape slides for the forward and aft entry and service doors to determine the part number and service bulletin number stenciled on the escape slide girt, and modification of the escape slide assemblies. This AD also requires concurrent modification of the escape slide latch assemblies; concurrent inspection of the escape slides to determine the part number and service bulletin number stenciled on the escape slide girts, and replacement of the trigger housing on the regulator valve with an improved trigger housing if necessary; and concurrent replacement of the rod in the pilot valve regulator with a new, improved rod; as applicable. This AD results from reports that certain escape slides did not automatically inflate when deployed or after the manual inflation cable was pulled. We are issuing this AD to prevent failure of an escape slide to inflate when deployed, which could result in the slide being unusable during an emergency evacuation and consequent injury to passengers or crewmembers.

DATES: This AD is effective January 2, 2009.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of January 2, 2009.

The Director of the Federal Register previously approved the incorporation

by reference of Boeing Service Bulletin 737-25-1404, dated May 25, 2000 on August 28, 2001 (66 FR 38361, July 24, 2001).

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207; telephone (206) 544-9990; fax (206) 766-5682; e-mail DDCS@boeing.com; Internet <https://www.myboeingfleet.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Robert K. Hettman, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6457, fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to certain Boeing Model 737-600, -700, -700C, -800 and -900 series airplanes. That NPRM was published in the **Federal Register** on February 15, 2008 (73 FR 8833). That NPRM proposed to require an inspection of the escape slides for the forward and aft entry and service doors to determine the part number and service bulletin number stenciled on the escape slide girt, and modification of the escape slide assemblies. That NPRM also proposed to require concurrent modification of the escape slide latch assemblies; concurrent inspection of the escape slides to determine the part number and service bulletin number stenciled on the escape slide girts, and replacement of the trigger housing on the regulator valve with an improved trigger housing if necessary; and concurrent replacement of the rod in the pilot valve

regulator with a new, improved rod; as applicable.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received from the three commenters.

Support for the NPRM

Boeing concurs with the contents of the proposed rule.

Requests To Refer to Additional Goodrich Service Bulletin

Goodrich, and Air Transport Association (ATA) on behalf of one of its members, American Airlines (AA), request that Boeing revise Boeing Service Bulletin 737-25-1491, dated April 23, 2007 (cited in the NPRM as the appropriate source of service information for accomplishing certain actions specified in the NPRM), to include a reference to Goodrich Service Bulletin 5A3307-25-339, Revision 2, dated March 31, 2004, as an alternative method of compliance (AMOC) to BFGoodrich Service Bulletin 25-308, dated January 21, 2000 (cited in the NPRM as a source of service information for accomplishing certain other actions specified in the NPRM). ATA and AA note that this service bulletin modifies the applicable slide to the latest standard offered by Goodrich. AA and Goodrich suggest that if Boeing Service Bulletin 737-25-1491, dated April 23, 2007, is not revised, the AD should state that it does not apply to Goodrich part number (P/N) 5A3307-5 slides and that Goodrich Service Bulletin 5A3307-25-339, Revision 2, dated March 31, 2004, be identified as an AMOC for the slide portion of the AD.

We disagree with the request to revise the AD to refer to Goodrich Service Bulletin 5A3307-25-339, Revision 2, dated March 31, 2004. There are significant differences in the actions between BFGoodrich Service Bulletin 25-308, dated January 21, 2000 and Goodrich Service Bulletin 5A3307-25-339, Revision 2, dated March 31, 2004. Therefore, any request to use the procedures in Goodrich Service Bulletin 5A3307-25-339 is best handled through the AMOC process. Under the provisions of paragraph (k) of the AD, we will consider requests for approval of an AMOC if sufficient data are submitted to substantiate that the change would provide an acceptable level of safety. We have not changed the AD in this regard.

Request To Revise Unsafe Condition

Goodrich notes that paragraph (g)(1) of the NPRM addresses an unsafe