

Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on January 15, 2015.

John P. Piccola, Jr.,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-01218 Filed 1-23-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0081; Directorate Identifier 2014-NM-170-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes. This proposed AD was prompted by reports of fluid entry and accumulation in the aft equipment bay. This proposed AD would require modifying the aft equipment bay. We are proposing this AD to prevent excessive quantities of flammable fluid accumulation in the aft equipment bay. Flammable fluid entry and accumulation in the aft equipment bay, in excessive quantities, could exceed safe levels maintained by the drainage and ventilation system.

DATES: We must receive comments on this proposed AD by March 12, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0081; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-0081; Directorate Identifier 2014-NM-170-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation, which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2014-25,

dated August 7, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes. The MCAI states:

There have been two reports of fluid entry and accumulation in the aft equipment bay. The leaked fluid in the first incident was fuel and the fluid in the second incident was test dye. Further investigation revealed that leaked fluid from the aft fuel tank drain entered the bay through the slot in the door latch mechanism.

Flammable fluid entry and accumulation in the aft equipment bay, in excessive quantities, could exceed safe levels maintained by the drainage and ventilation system.

Bombardier Inc. has issued several Service Bulletins (SB) to modify the Aft Equipment Bay by installing a cover to the door latch mechanism in order to reduce the risk of fuel entry into it. This [Canadian] AD mandates the incorporation of the applicable Bombardier Inc. SBs to rectify this problem.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0081.

Related Service Information

Bombardier has issued the following service information:

- Bombardier Service Bulletin 700-1A11-52-019, dated March 29, 2012.
- Bombardier Service Bulletin 700-52-042, dated March 29, 2012.
- Bombardier Service Bulletin 700-52-5007, dated March 29, 2012.
- Bombardier Service Bulletin 700-52-6007, dated March 29, 2012.

The service information describes procedures for the modification of the aft equipment compartment door. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 60 airplanes of U.S. registry.

We also estimate that it would take about 8 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about 720 per product. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$84,000, or \$1,400 per product.

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2015-0081; Directorate Identifier 2014-NM-170-AD.

(a) Comments Due Date

We must receive comments by March 12, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes, certificated in any category, serial numbers 9001 through 9476 inclusive and 9998.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by reports of fluid entry and accumulation in the aft equipment bay. We are issuing this AD to prevent excessive quantities of flammable fluid accumulation in the aft equipment bay. Flammable fluid entry and accumulation in the aft equipment bay, in excessive quantities, could exceed safe levels maintained by the drainage and ventilation system.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 24 months after the effective date of this AD, modify the aft equipment bay, in accordance with the Accomplishment Instructions of the applicable service information specified in paragraphs (g)(1) through (g)(4) of this AD.

(1) For Model BD-700-1A10 airplanes, serial number 9002 through 9312 inclusive, 9314 through 9380 inclusive, and 9384

through 9429 inclusive: Bombardier Service Bulletin 700-52-042, dated March 29, 2012.

(2) For Model BD-700-1A10 airplanes, serial numbers 9381 and 9432 through 9476 inclusive: Bombardier Service Bulletin 700-52-6007, dated March 29, 2012.

(3) For Model BD-700-1A11 airplanes, serial numbers 9127 through 9383 inclusive, 9389 through 9400 inclusive, 9404 through 9431 inclusive, and 9998: Bombardier Service Bulletin 700-1A11-52-019, dated March 29, 2012.

(4) For Model BD-700-1A11 airplanes, serial numbers 9386, 9401, and 9445 through 9474 inclusive: Bombardier Service Bulletin 700-52-5007, dated March 29, 2012.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-25, dated August 7, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0081.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on January 15, 2015.

John P. Piccola, Jr.,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-01217 Filed 1-23-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-151416-06]

RIN 1545-BG21

Certain Distributions Treated as Sales or Exchanges; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice of proposed rulemaking.

SUMMARY: This document contains corrections to a notice of proposed rulemaking (REG-151416-06) that was published in the **Federal Register** on Monday, November 3, 2014 (79 FR 65151), that prescribe how a partner should measure its interest in a partnership's unrealized receivables and inventory items, and that provide guidance regarding the tax consequences of a distribution that causes a reduction in that interest.

DATES: Written or electronic comments and request for a public hearing for the notice of proposed rulemaking at 79 FR 65151, November 3, 2014, are still being accepted and must be received by February 2, 2015.

FOR FURTHER INFORMATION CONTACT: Allison R. Carmody, at (202) 317-5279 or Frank J. Fisher, at (202) 317-6850 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The notice of proposed rulemaking published Monday, November 3, 2014 (79 FR 65151), is under section 751(b) of the Internal Revenue Code.

Need for Correction

As published, the notice of proposed rulemaking (REG-151416-06) contains errors that are misleading and are in need of clarification.

Correction to Publication

Accordingly, the notice of proposed rulemaking, FR Doc. 2014-25487, beginning on page 65151 in the issue of November 3, 2014, is corrected as follows:

■ 1. On page 65152, in the preamble, second column, twenty-fifth line from the top of the column, the language “example, Rev. Rul. 84-102 CB” is corrected to read “example, Rev. Rul. 84-102 (1984-2 CB)”.

■ 2. On page 65154, in the preamble, second column, sixth line from the bottom of the second full paragraph, the language “751(b) in situations in which 751(b)” is corrected to read “751(b) in situations in which section 751(b)”.

■ 3. On page 65155, in the preamble, third column, first and second lines from the bottom of the first full paragraph, the language “must disclose its position on Form 8275, Disclosure Statement.” is corrected to read “must disclose its position on Form 8275-R, Regulation Disclosure Statement.”.

§ 1.751-1 [Corrected]

■ 4. On page 65160, second column, sixteenth line of paragraph (b)(2)(ii), the language “takes into account any section 743 basis” is corrected to read “takes into account any section 743(b) basis”.

■ 5. On page 65160, third column, ninth line of paragraph (b)(2)(iii)(A), the language “taking into account any section 743” is corrected to read “taking into account any section 743(b)”.

■ 6. On page 65163, second column, the twenty-fourth through the twenty-sixth lines of paragraph (f), the language “this section consistently for all partnership sales, exchanges, and distributions, including for any” is corrected to read “this section, and proposed § 1.704-1(b)(2)(iv)(f), consistently for all partnership sales, exchanges, and distributions occurring on or after November 3, 2014, including for any”.

■ 7. On page 65165, second column, paragraph (g) *Example 4.* (ii)(B), the eleventh line, the language “immediately before the distribution are \$25” is corrected to read “immediately before the distribution is \$25”.

§ 1.755-1 [Corrected]

■ 8. On page 65172, second column, paragraph (c)(2)(vi), the twentieth line, the language “and (v), would have applied if no” is corrected to read “or (v), would have applied if no”.

■ 9. On page 65173, first column, paragraph (c)(6) *Example 2.* (vi)(D), the second line, the language “\$9 remaining section 743(b) adjustments is” is corrected to “\$9 remaining section 743(b) adjustment is”.

■ 10. On page 65173, first column, paragraph (c)(6) *Example 2.* (vi)(D), the eighth line from the bottom of the paragraph, the language “section 743(b) adjustments is not taken into” is

corrected to “section 743(b) adjustment is not taken into”.

Martin V. Franks,

Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration).

[FR Doc. 2015-01258 Filed 1-23-15; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF DEFENSE

Office of the Secretary

32 CFR Part 199

[DOD-2012-HA-0146]

RIN 0720-AB47

TRICARE; Reimbursement of Long Term Care Hospitals

AGENCY: Office of the Secretary, Department of Defense (DoD).

ACTION: Proposed rule.

SUMMARY: This proposed rule requests public comment on proposed implementation for Long Term Care Hospitals (LTCHs) the statutory provision at title 10, United States Code (U.S.C.), section 1079(j)(2) that TRICARE payment methods for institutional care be determined, to the extent practicable, in accordance with the same reimbursement rules as those that apply to payments to providers of services of the same type under Medicare. This proposed rule sets forth the proposed regulation modifications necessary to implement a TRICARE reimbursement methodology similar to that applicable to Medicare beneficiaries for inpatient services provided by LTCHs.

DATES: Written comments received at the address indicated below by March 27, 2015 will be accepted.

ADDRESSES: You may submit comments, identified by docket number or Regulatory Information Number (RIN) and title, by either of the following methods:

The Web site: <http://www.regulations.gov>. Follow the instructions for submitting comments.

Mail: Federal Docket Management System Office, Room 3C843, 1160 Defense Pentagon, Washington, DC 20301-1160.

Instructions: All submissions received must include the agency name and docket number or RIN for this **Federal Register** document. The general policy for comments and other submissions from members of the public is to make these submissions available for public viewing on the Internet at <http://www.regulations.gov>.