

(b) U.S. Department of Agriculture kernel color standards, PEC-MC-1, illustrate the color intensities implied by the terms “golden,” “light brown,” “medium brown,” and “dark brown” referred to in paragraph (a) of this section.

■ 4. In § 51.1437, Table I is amended by removing the entry “Midget” and adding in its place the entry “Extra small” to read as follows:

**§ 51.1437 Size classifications for halves.**

\* \* \* \* \*

\* \* \* \* \*

TABLE I

Size classifications for halves	Number of halves per pound
* * * * *	
Extra small .....	751 or more.

■ 5. In § 51.1438, Table II and Table III are amended by removing the entry “Midget pieces” and adding in its place the entry “Extra small pieces” to read as follows:

**§ 51.1438 Size classifications for pieces.**

\* \* \* \* \*

TABLE II

Size classification	Maximum diameter (will pass through round opening of following diameter)	Minimum diameter (will not pass through round opening of the following diameter) (inch)
* * * * *		
Extra small pieces .....	3/16 inch .....	1/16
* * * * *		

TABLE III  
[Percent]

Size classification	Total tolerance for offsize pieces	Tolerance (included in total tolerance) for pieces smaller than	
		2/16	1/16 inch
* * * * *			
Extra small pieces .....	15	.....	2
* * * * *			

■ 6. Revise § 51.1443 to read as follows:

**§ 51.1443 Particles and dust.**

*Particles and dust* means, for all size designations except “extra small pieces” and “granules,” fragments of kernels which will pass through a round opening two-sixteenths inch in diameter.

Dated: October 3, 2018.

**Bruce Summers,**

*Administrator, Agricultural Marketing Service.*

[FR Doc. 2018-21845 Filed 10-5-18; 8:45 am]

**BILLING CODE 3410-02-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2018-0451; Product Identifier 2017-NM-172-AD; Amendment 39-19406; AD 2018-19-06]**

**RIN 2120-AA64**

**Airworthiness Directives; Dassault Aviation Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Dassault Aviation Model FALCON 900EX airplanes. This AD was prompted by reports of rejected take-offs

due to untimely inboard flap retraction. This AD requires modification of the slat/flap control wiring and replacement of the slat/flap control box with an improved box. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective November 13, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 13, 2018.

**ADDRESSES:** For service information identified in this final rule, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Standards Branch, 2200

South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0451.

**Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0451; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenues SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Dassault Aviation Model FALCON 900EX airplanes. The NPRM published in the **Federal Register** on May 30, 2018 (83 FR 24686). The NPRM was prompted by reports of rejected take-offs due to untimely inboard flap retraction. The NPRM proposed to require modification of the

slat/flap control wiring and replacement of the slat/flap control box with an improved box.

We are issuing this AD to address an uncommanded retraction of the inboard slats and flaps during take-off, and consequent reduced controllability of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0219, dated November 14, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Dassault Aviation Model FALCON 900EX airplanes. The MCAI states:

An occurrence was reported where, during the take-off run, a red CAS [crew alerting system] message “NO TAKE OFF” was displayed, and an aural warning was given. The flight crew elected to abort the take-off. The configuration of the affected aeroplane was SF1 and indicated airspeed (IAS) was at 100 kts. Investigations showed that the outboard slat extended microswitch, located at track #7, was not correctly adjusted. A design review revealed that this deficiency may affect only Falcon 900LX (commercial designation) without modification M5636, during take-off in SF1 configuration.

This condition, if not corrected, could lead to an uncommanded retraction of inboard slats and flaps during take-off, possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition, DA [Dassault Aviation] designed modification M6043 and published Service Bulletin (SB) F900EX-522 to provide instructions for embodiment of this modification in-service.

For the reasons described above, this [EASA] AD requires a wiring modification and replacement of the slat/flap control box with an improved box.

You may examine the MCAI in the AD docket on the internet at [http://](http://www.regulations.gov)

[www.regulations.gov](http://www.regulations.gov) by searching for and locating Docket No. FAA-2018-0451.

**Comments**

We gave the public the opportunity to participate in developing this final rule. We received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

We reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

**Related Service Information Under 1 CFR Part 51**

Dassault Aviation has issued Dassault Aviation Service Bulletin F900EX-522, also referred to as 522, dated March 8, 2017. This service information describes procedures for modifying the slat/flap control wiring and replacing the slat/flap control box. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Costs of Compliance**

We estimate that this AD affects 13 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification and replacement .....	22 work-hours × \$85 per hour = \$1,870 .....	\$8,495	\$10,365	\$134,745

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all known costs in our cost estimate.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures

the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the

Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2018–19–06 Dassault Aviation:

Amendment 39–19406; Docket No. FAA–2018–0451; Product Identifier 2017–NM–172–AD.

#### (a) Effective Date

This AD is effective November 13, 2018.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Dassault Aviation Model FALCON 900EX airplanes, certificated

in any category, serial number 240 and serial numbers 242 through 273 inclusive.

#### (d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

#### (e) Reason

This AD was prompted by reports of rejected take-offs due to untimely inboard flap retraction. We are issuing this AD to address an uncommanded retraction of the inboard slats and flaps during take-off, and consequent reduced controllability of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Modification and Replacement

Within 500 flight hours after the effective date of this AD, modify the slat/flap control wiring and replace the slat/flap control box having part number (P/N) 6–7061 with an improved control box, in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F900EX–522, also referred to as 522, dated March 8, 2017.

#### (h) Parts Installation Prohibition

After modification of an airplane as required by paragraph (g) of this AD, no person may install any slat/flap control box having P/N 6–7061 on that airplane.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2017–0219, dated November 14, 2017, for related information. This MCAI may be found in the AD docket on the internet at

<http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0451.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3226.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Aviation Service Bulletin F900EX–522, also referred to as 522, dated March 8, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201–440–6700; internet <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on August 30, 2018.

**Jeffrey E. Duven,**

*Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018–21466 Filed 10–5–18; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2018–0357; Product Identifier 2018–NM–035–AD; Amendment 39–19428; AD 2018–19–27]

**RIN 2120–AA64**

#### Airworthiness Directives; Dassault Aviation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Dassault Aviation Model FALCON 2000EX airplanes. This AD was