

# Rules and Regulations

Federal Register

Vol. 84, No. 109

Thursday, June 6, 2019

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-1004; Product Identifier 2018-NM-106-AD; Amendment 39-19642; AD 2019-10-03]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. This AD was prompted by reports of cracks caused by corrosion of the edge of the bore of the spot face and corrosion of the lug bore of certain side-strut support fitting lugs. This AD requires repetitive detailed inspections of the left and right side-strut support fitting lugs with bushings installed for any corrosion, any crack, or any severed lug; repetitive detailed and high frequency eddy current (HFEC) inspections of the left and right side-strut support fitting lugs with bushings removed for any corrosion or any crack; and applicable on-condition actions. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective July 11, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 11, 2019.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; phone: 562-797-1717; internet: <https://www.myboeingfleet.com>. You may view

this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1004.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1004; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** George Garrido, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5232; fax: 562-627-5210; email: [george.garrido@faa.gov](mailto:george.garrido@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. The NPRM published in the **Federal Register** on December 6, 2018 (83 FR 62741). The NPRM was prompted by reports of cracks caused by corrosion of the edge of the bore of the spot face and corrosion of the lug bore of certain side-strut support fitting lugs. The NPRM proposed to require repetitive detailed inspections of the left and right side-strut support fitting lugs with bushings installed for any corrosion, any crack, or any severed lug; repetitive detailed and HFEC inspections of the left and right side-strut support fitting lugs with bushings removed for any corrosion or any crack; and applicable on-condition actions.

We are issuing this AD to address cracks caused by corrosion, which could result in sudden loss of the side-strut support fitting joint and main landing gear attachment to the airplane, resulting in the collapse of a main landing gear.

#### Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

#### Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing stated that accomplishing Supplemental Type Certificate (STC) ST01219SE does not affect the actions specified in the proposed AD.

We concur with the commenter. We have redesignated paragraph (c) of the proposed AD as paragraph (c)(1) of this AD and added paragraph (c)(2) to this AD to state that installation of STC ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

#### Request To Change Format of Paragraphs (g) and (h) of the Proposed AD

Boeing requested that we eliminate paragraph (h) of the proposed AD and incorporate the information as paragraph (g)(2) of this AD. Boeing pointed out that the title of paragraph (g) of the proposed AD would change to "Required Actions," and that paragraphs (g)(1) and (g)(2) of this AD would apply to Group 7 and Groups 1 through 6, respectively. Boeing stated that this request is for consistency with previous ADs for Boeing airplanes.

We disagree that elimination of paragraph (h) of the proposed AD and incorporating the information as paragraph (g)(2) of this AD is necessary. Over time we have used both formats, but most recently we have been using the format that was utilized in the NPRM. We do not find that there is a difference in clarity of the required actions. We also find that the requested change does not affect the requirements

of this final rule in this case. We have not changed this AD in this regard.

**Request To Clarify ACO Branch Authority**

Boeing requested that we clarify the ACO branch that has the authority to approve AMOCs for this group of airplanes. Boeing pointed out that previous final rules for The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes have identified The Manager, Los Angeles ACO Branch, FAA, had the authority to approve AMOCs, even when the service bulletin was submitted for approval through the Seattle ACO Branch. Additionally, Boeing pointed out that previous ADs for The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes identified a Los Angeles ACO Branch specialist in the “Related Information” paragraph of the proposed rule, even when the service bulletin was submitted for approval through the Seattle ACO Branch.

We agree that clarification is necessary. Normally, in NPRMs for The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, we include the Manager, Los Angeles ACO Branch, as the designated approval authority for AMOCs. We have updated paragraph (j) of this AD to specify The Manager, Los Angeles ACO Branch. The Seattle ACO Branch is

responsible during drafting of the NPRM and final rule of an AD for The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. After publication of the final rule, responsibility for the product is transferred to the Los Angeles ACO Branch. Therefore, when we draft the final rule of an AD for The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, we also specify a specialist from the Los Angeles ACO Branch. We have updated paragraph (k) of this AD to include the responsible specialist from the Los Angeles ACO Branch.

**Conclusion**

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

**Related Service Information Under 1 CFR Part 51**

We reviewed Boeing Service Bulletin 737-53-1246, Revision 1, dated May 30, 2018. This service information describes procedures for repetitive detailed inspections of the left and right side-strut support fitting lugs at body station (BS) 685 with bushings installed for any corrosion, any crack, or any severed lug; repetitive detailed and HFEC inspections of the left and right side-strut support fitting lugs at BS 685 with bushings removed for any corrosion or any crack; and applicable on-condition actions. On-condition actions include, among other things, inspections, corrosion removal, and a preventative modification. Doing the repetitive detailed and HFEC inspections of the side-strut support fitting lugs at BS 685 with bushings removed terminates the repetitive detailed inspections of the side-strut support fitting lugs at BS 685 with bushings installed. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Costs of Compliance**

We estimate that this AD affects 302 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Repetitive detailed inspection of left and right side lugs with bushings installed.	17 work-hours × \$85 per hour = \$1,445 per inspection cycle.	\$0	\$1,445 per inspection cycle.	\$436,390 per inspection cycle.
Repetitive detailed and HFEC inspections of left and right side lugs with bushings removed.	29 work-hours × \$85 per hour = \$2,465 per inspection cycle.	0	\$2,465 per inspection cycle.	\$744,430 per inspection cycle.

We estimate the following costs to do any necessary on-condition actions that would be required. We have no way of

determining the number of aircraft that might need these on-condition actions:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
Up to 18 work-hour × \$85 per hour = \$1,530 per inspection cycle .....	Unknown .....	Up to \$1,530 per inspection cycle.

We have received no definitive data that would enable us to provide parts cost estimates for the on-condition inspections and repairs specified in this AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII,

Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2019–10–03 The Boeing Company:**  
Amendment 39–19642; Docket No.

FAA–2018–1004; Product Identifier  
2018–NM–106–AD.

#### (a) Effective Date

This AD is effective July 11, 2019.

#### (b) Affected ADs

None.

#### (c) Applicability

(1) This AD applies to all The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

#### (d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

#### (e) Unsafe Condition

This AD was prompted by reports of cracks caused by corrosion of the edge of the bore of the spot face and corrosion of the lug bore of the body station (BS) 685 side-strut support fitting lugs. We are issuing this AD to address cracks caused by corrosion, which could result in sudden loss of the side-strut support fitting joint and main landing gear attachment to the airplane, resulting in the collapse of a main landing gear.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions for Group 7 Airplanes

For airplanes identified as Group 7 in Boeing Service Bulletin 737–53–1246, Revision 1, dated May 30, 2018: Within 120 days after the effective date of this AD, inspect the left and right side-strut support fitting lugs at BS 685 and do all applicable on-condition actions using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

#### (h) Required Actions for Groups 1 Through 6 Airplanes

For airplanes identified as Groups 1 through 6 in Boeing Service Bulletin 737–53–1246, Revision 1, dated May 30, 2018, except as specified in paragraph (i) of this AD: At the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Service Bulletin 737–53–1246, Revision 1, dated May 30, 2018, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Service Bulletin 737–53–1246, Revision 1, dated May 30, 2018.

#### (i) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Service Bulletin 737–53–1246, Revision 1, dated May 30, 2018, uses the

phrase “the Revision 1 date of this service bulletin,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Service Bulletin 737–53–1246, Revision 1, dated May 30, 2018, specifies contacting Boeing for repair instructions or for work instructions: This AD requires doing the repair or the work instructions and doing applicable on-condition actions using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (i) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### (k) Related Information

For more information about this AD, contact George Garrido, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5232; fax: 562–627–5210; email: george.garrido@faa.gov.

**(I) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 737-53-1246, Revision 1, dated May 30, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; phone: 562-797-1717; internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 20, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019-11790 Filed 6-5-19; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0801; Product Identifier 2017-NM-147-AD; Amendment 39-19632; AD 2019-08-11]

**RIN 2120-AA640**

**Airworthiness Directives; Bombardier, Inc., Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are superseding Airworthiness Directive (AD) 2008-24-14, which applied to all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. AD 2008-24-14 required revising the instructions for continued airworthiness to incorporate certain airworthiness limitations for the main landing gear (MLG) trunnion fitting assembly. This AD requires revising the maintenance or inspection program, as applicable, to

incorporate certain airworthiness limitations (AWLs). This AD also requires reworking the trunnion fitting in order to meet new structural safe-life limits. This AD was prompted by reports of cracks on the MLG trunnion fitting during fatigue testing; the introduction of new AWL tasks with revised inspection, modification, and safe-life requirements; and a determination that the trunnion fitting lower flange and both forward and aft bore holes are also subject to fatigue cracking. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective July 11, 2019.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 11, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of December 19, 2008 (73 FR 73785, December 4, 2008).

**ADDRESSES:** For service information identified in this final rule, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0801.

**Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0801; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Aziz Ahmed, Aerospace Engineer, Airframe

and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7329; fax 516-794-5531.

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2008-24-14, Amendment 39-15758 (73 FR 73785, December 4, 2008) (“AD 2008-24-14”). AD 2008-24-14 applied to all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The NPRM published in the **Federal Register** on October 1, 2018 (83 FR 49317). The NPRM was prompted by reports of cracks on the MLG trunnion fitting during fatigue testing; the introduction of new AWL tasks with revised inspection, modification, and safe-life requirements; and a determination that the trunnion fitting lower flange and both forward and aft bore holes are also subject to fatigue cracking. The NPRM proposed to require revising the maintenance or inspection program, as applicable, to incorporate certain AWLs. The NPRM also proposed to require reworking the trunnion fitting in order to meet new structural safe-life limits. We are issuing this AD to address fatigue cracking of the MLG trunnion fitting. Failure of the MLG trunnion fitting could result in MLG collapse.

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2017-27, dated August 2, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The MCAI states:

Cracks on the main landing gear (MLG) trunnion fitting web discovered during fatigue testing led to the issuance of [Canadian] AD CF-2008-21 [which corresponds to FAA AD 2008-24-14], which mandated new inspection requirements to ensure that fatigue cracking of the trunnion web would be detected and corrected.

Additional fatigue test article findings and in-service findings have shown that the trunnion fitting lower flange and both forward and aft bore holes are also subject to fatigue cracking. Failure of the main landing gear trunnion fitting could result in the collapse of the main landing gear. Bombardier Inc. has decided to implement a series of design changes to improve the fatigue life of the trunnion fitting that is now a safe-life assembly.

New and revised Airworthiness Limitation (AWL) tasks for the MLG trunnion fitting