

Rules and Regulations

Federal Register

Vol. 80, No. 141

Thursday, July 23, 2015

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF AGRICULTURE

Animal and Plant Health Inspection Service

7 CFR Part 319

Foreign Quarantine Notices

CFR Correction

In Title 7 of the Code of Federal Regulations, Parts 300 to 399, revised as of January 1, 2015, on page 372, in § 319.56–57, paragraph (c)(2) is correctly reinstated to read as follows:

§ 319.56–57 Sand pears from China.

* * * * *

(c) * * *

(2) Packinghouses must have a tracking system in place to readily identify all sand pears that enter the packinghouse destined for export to the United States back to their place of production.

* * * * *

[FR Doc. 2015–18071 Filed 7–22–15; 8:45 am]

BILLING CODE 1505–01–D

DEPARTMENT OF AGRICULTURE

Commodity Credit Corporation

7 CFR Part 1412

Agriculture Risk Coverage, Price Loss Coverage, and Cotton Transition Assistance Programs

CFR Correction

In Title 7 of the Code of Federal Regulations, Parts 1200 to 1599, revised as of January 1, 2015, on page 516, in § 1412.45, in paragraph (b)(3), the term “P&CP” is replaced with the term “planted”.

[FR Doc. 2015–18072 Filed 7–22–15; 8:45 am]

BILLING CODE 1505–01–D

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2015–2906; Directorate Identifier 2014–SW–068–AD; Amendment 39–18213; AD 2015–15–04]

RIN 2120–AA64

Airworthiness Directives; Bell Helicopter Textron, Inc.

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bell Helicopter Textron, Inc. (Bell), Model 204B, 205A, 205A–1, and 212 helicopters. This AD requires removing a certain part-numbered main rotor (M/R) blade grip (grip) from service. This AD is prompted by an error in a parts manufacturer approval (PMA) that incorrectly allows installation of the grips on the Bell Model 212. The actions specified in this AD are intended to prevent grip failure, separation of the M/R blade, and subsequent loss of control of the helicopter.

DATES: This AD becomes effective August 7, 2015. We must receive comments on this AD by September 21, 2015.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202–493–2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590–0001.

- *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD

docket contains this AD, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For Timken service information identified in this AD, contact Timken Alcor Aerospace Technologies, Inc., Aftermarket Customer Service, 3110 N. Oakland, Mesa, AZ 85215; telephone 1–480–606–3130; email timkenaftermarketsales@timken.com; or at <http://www.timken.com/en-us/solutions/aerospace/aftermarket/Pages/default.aspx>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT:

Scott Franke, Aviation Safety Engineer, Fort Worth Aircraft Certification Office, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222–5170; email scott.franke@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments prior to it becoming effective. However, we invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that resulted from adopting this AD. The most helpful comments reference a specific portion of the AD, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit them only one time. We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this rulemaking during the comment period. We will consider all the comments we receive and may conduct additional rulemaking based on those comments.