

proposed AD, that it would take zero additional work hours per engine to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$7,667 per engine, based on the estimated current part cost, prorated downward by a factor equal to the quotient of the difference between the original cyclic life limit (9000 cycles) and the revised cyclic life limit (6000 cycles) divided by the original cyclic life limit. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$1,150,000.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

General Electric Company: Docket No. 95-ANE-41.

Applicability: General Electric Company (GE) Models CF34-1A, -3A, and -3A2 turbofan engines, with high pressure compressor (HPC) stage 1 rotor disks, part number 6040T79G01, installed. These engines are installed on but not limited to Canadair Limited Model CL-600-2A12 and CL-600-2B16 aircraft.

Note: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the Federal Aviation Administration (FAA). This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any engine from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent HPC stage 1 rotor disk rupture, engine failure, and damage to the aircraft, accomplish the following:

(a) Remove from service HPC stage 1 rotor disks prior to accumulating 6,000 cycles in service since new, and replace with a serviceable part.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. The request should be forwarded through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

Issued in Burlington, Massachusetts, on December 8, 1995.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 95-30645 Filed 12-15-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-128-AD]

Airworthiness Directives; Jetstream Model 4101 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Jetstream Model 4101 airplanes. This proposal would require an inspection to verify the proper position of "door open" placards on the inside of the main entrance door, and replacement with new placards appropriately positioned, if necessary. This proposal is prompted by a report that the "door open" placards on the inside of the main entrance door, as currently installed, may not be visible to passengers or flightcrew when the door handle is in the open position. The actions specified by the proposed AD are intended to ensure that certain placards on the inside of the main entrance door are clearly visible and perform their intended function in the event of an emergency evacuation.

DATES: Comments must be received by January 23, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-128-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such

written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-128-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-128-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on certain Jetstream Model 4101 airplanes. The CAA advises that the "door open" placards on the inside of the main entrance door may not be properly installed (that is, aligned with the door handle when it is in the "open" position), as required by section 25.811 (e) of the Federal Aviation Regulations (14 CFR 25.811), "Emergency exit marking." The placards are currently installed at imprecise locations, since the type design data was not explicit in defining the installation locations. Therefore, these placards may not be visible to the passengers or flightcrew during an emergency evacuation, and consequently, do not fulfill the intent of the regulations, which is to ensure that these placards are visible and properly aligned with the door handle when it is in the "open" position. This condition, if not corrected, could delay or impede

the evacuation of passengers during an emergency.

Jetstream has issued Service Bulletin J41-11-007, dated May 10, 1995, which describes procedures for a one-time visual inspection to verify the proper position of certain placards on the inside of the main entrance door, and removal of the placard and installation of a new placard, if necessary. The CAA classified this service bulletin as mandatory in order to assure the continued airworthiness of these airplanes in the United Kingdom.

This airplane model is manufactured in the United Kingdom and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist on other airplanes of the same type design, the proposed AD would require a one-time visual inspection to verify the proper position of certain placards on the inside of the main entrance door, and removal of the placard and installation of a new placard, if necessary. The actions would be required to be accomplished in accordance with the service bulletin described previously.

The FAA estimates that 25 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would be supplied by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$1,500, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore,

in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40101, 40113, 44701.

39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Jetstream Aircraft Limited: Docket 95-NM-128-AD.

Applicability: Model 4101 airplanes, constructors numbers 41004 through 41046 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition

addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To ensure that certain placards on the inside of the main entrance door are clearly visible and properly aligned, accomplish the following:

(a) Within 4 months after the effective date of this AD, perform a one-time visual inspection to verify the proper position of the door open placards on the inside of the main entrance door, in accordance with Jetstream Service Bulletin J41-11-007, dated May 10, 1995. If any placard is found to be improperly positioned, prior to further flight, remove the placard and install a new placard in the specified position, in accordance with the service bulletin.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on December 11, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-30644 Filed 12-15-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-CE-61-AD]

Airworthiness Directives; Brackett Aircraft Company, Inc. Air Filter Assemblies Installed on Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to supersede AD 95-03-02, which currently requires repetitively inspecting (visually) the air filter frame for a loose or deteriorating gasket on airplanes incorporating certain Brackett air filter assemblies. The proposed action retains the repetitive inspection

and possible replacement requirements as contained in AD 95-03-02, and would incorporate additional Brackett air filter assemblies to the applicability of that AD. Additionally, it would provide a terminating action for the repetitive inspection. The Federal Aviation Administration's determination that these additional Brackett air filter assemblies should be inspected and replaced prompted this AD action. The actions specified by the proposed AD are intended to prevent gasket particles from entering the carburetor because of air filter gasket failure, which, if not detected and corrected, could result in partial or complete loss of engine power and loss of control of the airplane.

DATES: Comments must be received on or before February 20, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-CE-61-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Brackett Aircraft Company, Inc., 7045 Flightline Drive, Kingman, Arizona 86401. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Elizabeth Bumann, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (310) 627-5265; facsimile (310) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before

and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 95-CE-61-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-CE-61-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

AD 95-03-02 was published in the Federal Register on August 25, 1994 (59 FR 43784) and applies to airplanes that have a certain Brackett air filter neoprene gasket installed in accordance with Supplemental Type Certificate (STC) SA71GL. The action requires repetitively inspecting (visually) the air filter frame for a loose or deteriorated gasket, and replacing any gasket found loose or deteriorated.

The FAA's continuing investigation of these Brackett neoprene gasket air filter's failure and the continuing unsafe condition described in AD 95-03-02 suggests that a superseding action be proposed. The FAA has discovered that additional Brackett air filters with the same neoprene gasket design are installed as original equipment and in accordance with STC SA693CE on certain additional airplanes. These airplanes would also be subject to air filter assembly failure.

After examining the circumstances and reviewing all available information related to the information described above, the FAA has determined that AD action should be taken to prevent gasket particles from entering the carburetor because of air filter gasket failure, which could result in partial or complete loss of engine power.

Since an unsafe condition has been identified that is likely to exist or develop in other Brackett air filter frame assemblies of the same type design, the proposed AD would supersede AD 95-03-02 with a new AD that would require incorporating additional Brackett air filter assemblies to the applicability paragraph of AD 95-03-02,