Oil spills into the storm drain

Car Wash operations spilling waste into the storm drain



Unchanged Return-Air-Filter

Mechanical Room Air ducts



Return Air Filter changed twice in seventeen years. Last change of Return Air Filter recorded ten years ago,



Exhaust from Mechanical Room

Flammable Storage

DRAFT

7 -Flammables Storage

All facilities face a severe shortage of storage space. This includes a lack of storage space for flammable chemicals

Flammable Storage

Propane tank viewed from within the garage with flammable storage – which is used as a laundry

759

Flammable Storage

Flammable Chemicals sharing space with the laundry, washer and dryer

Front Entrance and Reception

DRAFT

8 -Front Entrance – Reception

Being public facilities, the detention and corrections facilities are accessible to the public, but without an appropriate and secure 'visitors entrance'. The Central Control station officer serves as a receptionist. For a lack of separation and appropriate barrier, this officer is in jeopardy of being attacked and/or killed by an irate visitor who has direct and unfettered access up to the officer.

Front Entrance and Reception

A straight shot from the parking lot as pictured here, can jeopardize the officer through the window opening – that is meant for the visitors to communicate with the reception

762

Front Entrance and Reception

A close-up of the window opening that is accessible through the open door at the front entrance. Two pieces of thin steel are used to reduce the size of the opening. A piece of cardboard is then used to block the center opening.

Front Entrance and Reception

Visitors counter. See picture below for the other side of this public counter.

Front Entrance and Reception

Central Control Station in operation

765

Front Entrance and Reception

Multiple monitors that need attention, at the Central Control Station

Front Entrance and Reception



Officers at the Central Control Station

Front Entrance and Reception



Key Ring with the single master key for the facility left at the public counter accessible to the public – same room as in the previous picture

Front Entrance and Reception

When alerted, a cardboard barrier was used to close the opening in the window – But the master key is still left in place.

769

Front Entrance and Reception



Central Control Station officer is accessible through the public window, jeopardizing her life and safety

Front Entrance and Reception



Central Control Station officer is accessible through the public window, jeopardizing her life and safety

Front Entrance and Reception



Close-up of the public access window depicted on the picture on the previous page

Front Entrance and Reception



Public Access to the Central Control Station officer through the window – at far left

Front Entrance and Reception



Central Control Station Officer is in jeopardy for her life and safety, through the opening in the public access window

Front Entrance and Reception



Central Control Station Officer is in jeopardy for her life and safety, through the opening in the public access window

Worn out blankets

DRAFT

9 - Worn out Blankets

A random check indicated an excessively high percentage of worn out blankets and mattress. A large number of facilities depend on business donations, charitable donations and contributions from family if they can afford to provide such contribution