

Agricultural Marketing Service, USDA

§ 42.102

§ 37.16 OMB assigned numbers.

The information collection and recordkeeping requirements contained in this part have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act, 44 U.S.C. Chapter 35 and have been assigned OMB Control Number 0581-0183.

PARTS 38-41 [RESERVED]

PART 42—STANDARDS FOR CONDITION OF FOOD CONTAINERS

Subpart A—Definitions

Sec.

- 42.101 Meaning of words.
- 42.102 Definitions, general.

Subpart B—Procedures for Stationary Lot Sampling and Inspection

- 42.103 Purpose and scope.
- 42.104 Sampling plans and defects.
- 42.105 Basis for selection of sample.
- 42.106 Classifying and recording defects.
- 42.107 Lot acceptance criteria.
- 42.108 Normal, tightened or reduced inspection.
- 42.109 Sampling plans for normal condition of container inspection, Tables I and I-A.
- 42.110 Sampling plans for tightened condition of container inspection, Tables II and II-A.
- 42.111 Sampling plans for reduced condition of container inspection, Tables III and III-A; and limit number for reduced inspection, Table III-B.
- 42.112 Defects of containers: Tables IV, V, VI, and VII.
- 42.113 Defects of label, marking, or code: Table VIII.

Subpart C—Skip Lot Sampling and Inspection Procedures

- 42.120 Description and qualification.
- 42.121 Sampling and inspection procedures.
- 42.122 Applicability of other procedures.
- 42.123 Flow diagram for skip lot sampling and inspection.

Subpart D—On-Line Sampling and Inspection Procedures

- 42.130 Description and qualifications.
- 42.131 Selection of samples.
- 42.132 Determining cumulative sum values.
- 42.133 Portion of production acceptance criteria.
- 42.134 Disposition of rejected portions of production.

- 42.135 Normal, tightened or reduced on-line inspection.
- 42.136 Applicability of other procedures.

Subpart E—Miscellaneous

- 42.140 Operating Characteristic (OC) curves for on-line sampling and inspection.
- 42.141 Obtaining Operating Characteristic (OC) curve information for skip lot sampling and inspection.
- 42.142 Curve for obtaining Operating Characteristic (OC) curve information for skip lot sampling and inspection.
- 42.143 Operating Characteristic (OC) curves for on-line sampling and inspection.

AUTHORITY: Secs. 203, 205, 60 Stat. 1087, as amended, 1090, as amended (7 U.S.C. 1622, 1624).

Subpart A—Definitions

§ 42.101 Meaning of words.

Words used in this part in the singular form shall be considered to import the plural, or vice versa, as the case may demand.

[31 FR 4687, Mar. 19, 1966; 31 FR 4949, Mar. 25, 1966; Redesignated at 42 FR 32514, June 27, 1977 and at 46 FR 63203, Dec. 31, 1981]

§ 42.102 Definitions, general.

For the purpose of this part, unless the context otherwise requires, the following terms shall be construed, respectively, to mean:

Acceptable Quality Level (AQL). The maximum number of defects per hundred units (DHU) which is acceptable as a process average. Lots, or portions of production, having a quality level equal to a specified AQL will be accepted approximately 95 percent of the time when using the sampling plans prescribed for the AQL.

Acceptance Number (Ac). The number in a sampling plan that indicates the maximum number of defects permitted in a sample in order to consider a lot as meeting a specific requirement.

Administrator. The Administrator of the Agricultural Marketing Service (AMS) of the Department or any other officer or employee of the Agency to whom there has heretofore been delegated, or to whom there may hereafter be delegated, the authority to act in his stead.

Basic Inspection Period. A specified period of consecutive production designated for on-line inspection (e.g., one