40 CFR Ch. I (7-1-10 Edition)

ST	F126–EGU	F126-NEGU	Total
WV	26,859	2,184	29,043
Total	265,078	24,905	289,983

APPENDIX D TO PART 97—FINAL SECTION 126 RULE: STATE COMPLIANCE SUPPLEMENT POOLS FOR THE SECTION 126 FINAL RULE (TONS)

State	Compliance supplement pool
Delaware	168
District of Columbia	0
Indiana	2,454
Kentucky	7,314
Maryland	3,882
Michigan	9,398
New Jersey	1,550
New York	1,379
North Carolina	10,737
Ohio	22,301
Pennsylvania	15,763
Virginia	5,504
West Virginia	16,709
Total	97,159

PART 98—MANDATORY **GREENHOUSE GAS REPORTING**

Subpart A—General Provisions

Sec.

- 98.1 Purpose and scope.
- Who must report?
- 98.3 What are the general monitoring, reporting, recordkeeping and verification requirements of this part?
- 98.4 Authorization and responsibilities of the designated representative.
- 98.5 How is the report submitted?
- 98.6 Definitions.
- 98.7 What standardized methods are incorporated by reference into this part?
- 98.8 What are the compliance and enforcement provisions of this part?
- 98.9 Addresses.
- TABLE A-1 TO SUBPART A OF PART 98-GLOB-AL WARMING POTENTIALS (100-YEAR TIME HORIZON)
- TABLE A-2 TO SUBPART A OF PART 98—UNITS OF MEASURE CONVERSIONS

Subpart B [Reserved]

Subpart C—General Stationary Fuel **Combustion Sources**

- 98.30 Definition of the source category.
- 98.31 Reporting threshold.
- 98.32 GHGs to report.
- Calculating GHG emissions. 98.33
- 98.34 Monitoring and QA/QC requirements. 98.35 Procedures for estimating missing
- data.

- 98.36 Data reporting requirements.
- Records that must be retained.
- 98.38 Definitions.
- TABLE C-1 TO SUBPART C OF PART 98-DE-FAULT CO2 EMISSION FACTORS AND HIGH HEAT VALUES FOR VARIOUS TYPES OF FUEL
- TABLE C-2 TO SUBPART C OF PART 98-DE-FAULT CH4 AND N2O EMISSION FACTORS FOR VARIOUS TYPES OF FUEL
- TABLE C-2 TO SUBPART C OF PART 98-DE-FAULT CH_4 AND N_2O EMISSION FACTORS FOR VARIOUS TYPES OF FUEL

Subpart D—Electricity Generation

- 98.40 Definition of the source category.
- Reporting threshold. 98.41
- GHGs to report. 98.42
- Calculating GHG emissions. 98.43
- Monitoring and QA/QC requirements. 98.44
- Procedures for estimating missing 98.45data.
- 98.46 Data reporting requirements.
- 98.47 Records that must be retained.
- 98.48 Definitions.

Subpart E—Adipic Acid Production

- 98.50 Definition of source category.
- 98.51 Reporting threshold.
- 98 52 GHGs to report
- 98.53 Calculating GHG emissions.
- 98 54 Monitoring and QA/QC requirements.
- 98.55 Procedures for estimating missing data.
- 98.56 Data reporting requirements.
- 98.57 Records that must be retained.
- 98.58 Definitions.