Section	Violation	Willful viola- tion
215.305 Stencilling of maintenance-of-way	1,000	2,000

¹A penalty may be assessed against an individual only for a willful violation. Generally, when two or more violations of these regulations are discovered with respect to a single freight car that is placed or continued in service by a railroad, the appropriate penalties set forth above are aggregated up to a maximum of \$16,000 per day. However, a failure to perform, with respect to a particular freight car, the predeparture inspection required by \$215.13 of this part will be treated as a violation separate and distinct from, and in addition to, any substantive violative conditions found on the car. The Administrator reserves the right to assess a penalty of up to \$100,000 for any violation where circumstances warrant. See 49 CFR part 209, appendix A. Failure to observe any condition for movement set forth in paragraphs (a) and (c) of \$215.9 will deprive the railroad of the benefit of the movement-for-repair provision and make the railroad and any responsible individuals liable for penalty under the particular regulatory section(s) concerning the substantive defect(s) present on the freight car at the time of movement. Maintenance-of-way equipment not stenciled in accordance with \$215.305 is subject to all requirements of this part. See \$215.3(c)(3).

[53 FR 52925, Dec. 29, 1988, as amended at 63 FR 11620, Mar. 10, 1998; 69 FR 30593, May 28, 2004; 72 FR 51196, Sept. 6, 2007; 73 FR 79701, Dec. 30, 2008]

APPENDIX C TO PART 215—FRA FREIGHT CAR STANDARDS DEFECT CODE

The following defect code has been established for use by FRA and State inspectors to report defects observed during inspection of freight cars. The purpose of the code is to establish a uniform language among FRA, States, and the railroad industry that will facilitate communication, recordkeeping, and statistical analyses. The code may not be substituted for the description of defects on bad order tags affixed to cars being moved for repair under §215.9. However, it may be used to supplement that description.

INDEX

General

- 215.009 Improper Movement of Defective Cars.
- 215.011 Designation of Qualified Persons.
- 215.013 Failure to Perform a Pre-departure Inspection.
- 215.015 Failure to Complete Initial Periodic Inspection as Required.

FREIGHT CAR COMPONENTS

Suspension System

- 215.103 Defective Wheel.
- 215.105 Defective Axle.
- Defective Plain Bearing Box: Gen-215.107eral.
- 215.109 Defective Plain Bearing Box: Journal Lubrication System.
- 215.111 Defective Plain Bearing.
- 215.113 Defective Plain Bearing Wedge.
- Defective Roller Bearing. 215.115
- Defective Roller Bearing Adapter. 215.117
- Defective Freight Car Truck. 215.119

Car Bodies

215.121 Defective Car Body.

Draft Sustem

- 215.123 Defective Couplers.
- 215.125 Defective Uncoupling Device.
- 215.127 Defective Draft Arrangement.

215.129 Defective Cushioning Device.

Restricted Equipment

215.203 Restricted Cars.

Stencilina

- 215.301 Improper Stenciling.
- 215.303 Improper Stenciling of Restricted Cars.
- 215.305 Improper Stenciling of Maintenanceof-Way Equipment.

Description of Defects

- 215.009 Failure to meet conditions for movement of defective cars for repairs.
- 215.011 Designation of Qualified Persons. (A)(1) Railroad fails to designate persons
- qualified to inspect freight cars;
- (2) Persons designated does not have knowledge and ability to inspect freight cars for compliance with the requirements of this part.
- (B) Railroad fails to maintain written record of:
- (1) Each designation in effect:
- (2) The basis for this designation.
- 215.013 Failure to perform pre-departure inspection.
- 215.015 Periodic Inspection.
 - (A) Railroad fails to perform the periodic inspection as required by June 30, 1980
 - (1) High utilization car built prior to December 31, 1977:
 - (2) Non-high utilization car built prior to December 31, 1971;
 - (B) A freight car improperly stenciled for periodic inspection.
- 215.103 Defective Wheel
- (A)(1) Flanges %" or less at %" above the tread:
- (2) Flanges 13/16" or less at 3/8" above the tread:
- (3) Flanges 3/4" or less at 3/8" above the tread:
- (B)(1) Flange is 11/2" or more from the tread to top of flange;

- (2) Flange is 1%" or more from the tread to top of flange;
- (3) Flange is 1¾".
- (C)(1) Rim thickness is 11/16" or less;
- (2) Rim thickness is 5%" or less:
- (3) Rim thickness is %16" or less;
- (D) Wheel cracked or broken in: (1) rim. (2) flange, (3) plate or (4) hub area.
- (E) Wheel chip or gouge in flange:
- (1) 1½" length and ½" in width or more;
- (2) 15%" length and 5%" in width or more;
- (3) 13/4" in length and 3/4" in width or more.
- (F) Wheel has slid flat spot or shelled spot:
- (1) $2^{1}/2^{\prime\prime}$ in length or more;
- (2) Has two adjoining flat spots each of which is 2" in length or greater;
- (3) A single flat spot 3" in length or more;
- (4) Has two adjoining flat spots one of which is at least 2" in length and the other is $2\frac{1}{2}$ or greater.
- (G) Has a loose wheel.
- (H) Overheated with discoloration extending: (1) More than 4"; (2) 41/2" or more.
- (I) A welded wheel on car that is not moving for repairs.
- 215 105 Defective Axle.
 - (A) Cracked or broken:
 - (1) Cracked 1' or less:
 - (2) Cracked greater than 1";
 - (3) Broken or cracked with visible separation of metal.
- (B) Gouge between wheel seats more than 1/8" in depth:
- (C) Broken or cracked end collar on plain bearing axle.
- (D) Overheated journal.
- (E) Surface of plain bearing journal or fillet has (1) ridge, (2) depression, (3) circumferential score, (4) corrugation, (5) scratch, (6) continuous streak, (7) pitting, (8) rust, (9) etching.
- 215.107 Defective plain bearing box.
 - (A) (1) Does not contain visible free oil;
 - (2) A journal box with dry pad.
 - (B) Lid is missing, broken or open except to receive service.
 - (C) Box has foreign matter that will damage bearing or prevent lubrication.
- 215.109 Defective plain bearing box: journal lubrication system.
 - (A) Pad torn half the length or width.
- (B) Scorched, burned or glazed.
- (C) Contains decaying or deteriorated fabric.
- (D) Has exposed core except by design of metal parts in contact with journal.
- (E)(1) Missing:
- (2) Not in contact with journal.
- 215.111 Defective plain bearing.
 - (A) Missing, cracked or broken. (B)(1) Bearing lining is loose;
 - (2) Broken out piece.
 - (C) Overheated as evidenced by:
 - (1) Melted babbit:
- (2) Smoke from hot oil;
- (3) Journal surface damaged.
- 215.113 Defective plain bearing wedge.

- (A) Missing
- (B) Cracked.
- (C) Broken
- (D) Not located in design position.
- 215.115 Defective roller bearing.
 - (A)(1) Overheated;
 - (2) Loose or missing cap screw;
 - (3) Roller bearing seal loose or damaged permitting loss of lubricant;
 - (4) Two or more missing cap screws.
 - (B)(1) Failure to inspect if involved in derailment:
- (2) Failure to disassemble if required under this part: (3) Failure to repair or replace defective
- roller bearings.
- 215.117 Defective roller bearing adapter.
 - (A) Cracked or broken
 - (B) Not in design position.
 - (C) Worn excessively as shown on Figure 1 in relief portion.
- 215.119 Defective freight car trucks.
 - (A)(1) Side frame or bolster broken:
- (2) Cracked 1/4" or more in transverse direction on tension member:
- (3) Cracked 1" or more in transverse direction on tension member.
- (B) Has ineffective snubbing devices.
- (C)(1) Missing or broken side bearing;
- (2) Side bearing in contact except by design:
- (3) Excessive side bearing clearance at one end of car:
- (4) Excessive side bearing clearance on opposite sides at diagonal ends of car.
- (D)(1) Has truck springs that will not maintain travel or load:
- (2) Truck springs that are compressed solid:
- (3) Has two springs broken in a cluster;
- (4) Has three or more springs broken.
- (E) Truck bolster and center plate interference preventing rotation.
- (F) Has broken beam shelf supports worn so that shelf will not support beam. 215.121 Defective car body.
 - (A) Improper clearance—less than $2\frac{1}{2}$ " from top of rail.

 - (B) Center sill is:
 - (1) Broken:
 - (2) Cracked more than 6":
 - (3) Bent or buckled more than 21/2" in any 6-foot length.
 - (C) Coupler carrier is:
 - (1) Broken:
 - (2) Missing:
 - (3) Non-resilient when used with coupler with F head.
 - (D) Car door not equipped with operative safety hangers.
 - (E) If center plate:
 - (1) Any portion missing;
 - (2) Broken or cracked as defined in this part
- (F) Broken side sills, crossbars or body bolster
- 215.123 Defective couplers.

Pt. 215, App. D

- (A) Coupler shank bent.
- (B) Coupler cracked in highly stressed area of head and shank.
- (C) Coupler knuckle broken.
- (D) Coupler knuckle pin or knuckle throw:
- (1) Missing;
- (2) Inoperative.
- (E) Coupler retainer pin lock:
- (1) Missing;
- (2) Broken.
- (F)(1) Coupler locklift is inoperative;
- (2) No anti-creep protection;
- (3) Coupler lock is (i) missing, (ii) inoperative, (iii) bent, (iv) cracked or (v) broken
- 215.125 Defective uncoupling device.
- (A) Fouling on curve.
- (B) Unintentional uncoupling.
- 215.127 Defective draft arrangement.
 - (A) Draft gear inoperative.
 - (B) Broken yoke.
 - (C) End of car cushioning unit:
 - (1) Leaking;
 - (2) Inoperative.
 - (D) Vertical coupler pin retainer plate:
 - (1) Missing;
 - (2) Has missing fastener.
 - (E) Draft key or key retainer:
 - (1) Inoperative;
 - (2) Missing.
- (F) Follower plate missing or broken.
- 215.129 Defective cushioning device unless effectively immobilized.
 - (A) Broken.
 - (B) Inoperative.
- (C) Missing parts.
- 215.203 Operating a restricted car, except under conditions approved by FRA.

Stenciling

- 215.301 Failure to stencil car number and built date on freight car as required.
- 215.303 Failure to stencil restricted car as required.
- 215.305 Failure to stencil maintenance-ofway equipment as required.

APPENDIX D TO PART 215—PREDEPARTURE INSPECTION PROCEDURE

At each location where a freight car is placed in a train and a person designated under §215.11 is not on duty for the purpose of inspecting freight cars, the freight car shall, as a minimum, be inspected for the imminently hazardous conditions listed below that are likely to cause an accident or casualty before the train arrives at its destination. These conditions are readily discoverable by a train crew member in the course of a customary inspection.

- 1. Car body:
- (a) Leaning or listing to side.
- (b) Sagging downward.
- (c) Positioned improperly on truck.
- (d) Object dragging below.
- (e) Object extending from side.

49 CFR Ch. II (10-1-10 Edition)

- (f) Door insecurely attached.
- (g) Broken or missing safety appliance.(h) Lading leaking from a placarded hazardous material car.
- 2. Insecure coupling.
- 3. Overheated wheel or journal.
- 4. Broken or extensively cracked wheel.
- 5. Brake that fails to release.
- 6. Any other apparent safety hazard likely to cause an accident or casualty before the train arrives at its destination.
- $[45~{\rm FR}~26711,~{\rm Apr.}~21,~1980,~{\rm as}~{\rm amended}~{\rm at}~73~{\rm FR}~79701,~{\rm Dec.}~30,~2008]$

PART 216—SPECIAL NOTICE AND EMERGENCY ORDER PROCE-DURES: RAILROAD TRACK, LO-COMOTIVE AND EQUIPMENT

Subpart A—General

Sec.

- 216.1 Application.
- 216.3 Definitions.
- 216.5 Delegation and general provisions.
- 216.7 Penalties.

Subpart B—Special Notice for Repairs

- 216.11 Special notice for repairs—railroad freight car.
- 216.13 Special notice for repairs—locomotive.
- 216.14 Special notice for repairs—passenger equipment.
- 216.15 Special notice for repairs—track class.216.17 Appeals.

Subpart C—Emergency Order—Track

- 216.21 Notice of track conditions.
- 216.23 Consideration of recommendation.
- 216.25 Issuance and review of emergency order.
- 216.27 Reservation of authority and discretion.

SOURCE: 41 FR 18657, May 6, 1976, unless otherwise noted.

Subpart A—General

§216.1 Application.

- (a) This part applies, according to its terms, to each railroad that uses or operates—
- (1) A railroad freight car subject to part 215 of this chapter;
- (2) A locomotive subject to 49 U.S.C. chapter 207 (49 U.S.C. 20701-03); or