Pt. 63, Subpt. DDDDD, Table 2

Table 2 to Subpart DDDDD of Part 63—Operating Limits for Boilers and PROCESS HEATERS WITH PARTICULATE MATTER EMISSION LIMITS As stated in §63.7500. you must comply with the applicable operating limits:

If you demonstrate compliance with applicable particulate matter emission limits using	You must meet these operating limits
1. Wet scrubber control	a. Maintain the minimum pressure drop and liquid flow-rate a or above the operating levels established during the per formance test according to §63.7530(c) and Table 7 to this subpart that demonstrated compliance with the applicable emission limit for particulate matter.
2. Fabric filter control	a. Install and operate a bag leak detection system according to § 63.7525 and operate the fabric filter such that the bag leak detection system alarm does not sound more than the percent of the operating time during each 6-month period or
Electrostatic precipitator control	b. This option is for boilers and process heaters that operate dry control systems. Existing boilers and process heaters must maintain opacity to less than or equal to 20 percen (6-minute average) except for one 6-minute period per hou of not more than 27 percent. New boilers and process heat ers must maintain opacity to less than or equal to 10 per cent opacity (1-hour block average).
	a. This option is for boilers and process heaters that operate dry control systems. Existing boilers and process heaters must maintain opacity to less than or equal to 20 percen (6-minute average) except for one 6-minute period per hou of not more than 27 percent. New boilers and process heat ers must maintain opacity to less than or equal to 10 per cent opacity (1-hour block average); or
	b. This option is only for boilers and process heaters that op erate additional wet control systems. Maintain the minimum voltage and secondary current or total power input of the electrostatic precipitator at or above the operating limits es tablished during the performance test according to § 63.7530(c) and Table 7 to this subpart that demonstrated compliance with the applicable emission limit for particulate matter.
4. Any other control type	This option is for boilers and process heaters that operate dry control systems. Existing boilers and process heaters mus maintain opacity to less than or equal to 20 percent (6 minute average) except for one 6-minute period per hour on to more than 27 percent. New boilers and process heaters must maintain opacity to less than or equal to 10 percen opacity (1-hour block average).

Heaters That Choose To Comply With the Alternative Total Selected METALS EMISSION LIMITS

As stated in § 63.7500, you must comply with the applicable operating limits:

If you demonstrate compliance with applicable mercury and/or total selected metals emission limits using	You must meet these operating limits
1. Wet scrubber control	Maintain the minimum pressure drop and liquid flow-rate at or above the operating levels established during the performance test according to § 63.7530(c) and Table 7 to this subpart that demonstrated compliance with the applicable emission limits for mercury and/or total selected metals.
2. Fabric filter control	a. Install and operate a bag leak detection system according to § 63.7525 and operate the fabric filter such that the bag leak detection system alarm does not sound more than 5 percent of the operating time during a 6-month period; or b. This option is for boilers and process heaters that operate dry control systems. Existing sources must maintain opacity to less than or equal to 20 percent (6-minute average) except for one 6-minute period per hour of not more than 27 percent. New sources must maintain opacity to less than or equal to 10 percent opacity (1-hour block average).