

Environmental Protection Agency

Pt. 63, Subpt. RRR, Table 2

TABLE 2 TO SUBPART RRR OF PART 63—SUMMARY OF OPERATING REQUIREMENTS FOR NEW AND EXISTING AFFECTED SOURCES AND EMISSION UNITS

Affected source/emission unit	Monitor type/operation/process	Operating requirements
All affected sources and emission units with an add-on air pollution control device. All affected sources and emission units subject to production-based (lb/ton of feed) emission limits <sup>a</sup> . Group 1 furnace, group 2 furnace, in-line fluxer and scrap dryer/delacquering kiln/ decoating kiln.	Emission capture and collection system.	Design and install in accordance with Industrial Ventilation: A Handbook of Recommended Practice; operate in accordance with OM&M plan. <sup>b</sup>
	Charge/feed weight or Production weight.	Operate a device that records the weight of each charge; Operate in accordance with OM&M plan. <sup>b</sup>
	Labeling .....	Identification, operating parameter ranges and operating requirements posted at affected sources and emission units; control device temperature and residence time requirements posted at scrap dryer/delacquering kiln/decoating kiln.
Aluminum scrap shredder with fabric filter.	Bag leak detector or .....	Initiate corrective action within 1-hr of alarm and complete in accordance with OM&M plan <sup>b</sup> ; operate such that alarm does not sound more than 5% of operating time in 6-month period.
	COM or .....	Initiate corrective action within 1-hr of a 6-minute average opacity reading of 5% or more and complete in accordance with OM&M plan. <sup>b</sup>
	VE .....	Initiate corrective action within 1-hr of any observed VE and complete in accordance with the OM&M plan. <sup>b</sup>
Thermal chip dryer with afterburner.	Afterburner operating temperature.	Maintain average temperature for each 3-hr period at or above average operating temperature during the performance test.
	Afterburner operation .....	Operate in accordance with OM&M plan. <sup>b</sup>
Scrap dryer/delacquering kiln/ decoating kiln with afterburner and lime-injected fabric filter.	Feed material .....	Operate using only unpainted aluminum chips.
	Afterburner operating temperature.	Maintain average temperature for each 3-hr period at or above average operating temperature during the performance test.
	Afterburner operation .....	Operate in accordance with OM&M plan. <sup>b</sup>
	Bag leak detector or .....	Initiate corrective action within 1-hr of alarm and complete in accordance with the OM&M plan; <sup>b</sup> operate such that alarm does not sound more than 5% of operating time in 6-month period.
	COM .....	Initiate corrective action within 1-hr of a 6-minute average opacity reading of 5% or more and complete in accordance with the OM&M plan. <sup>b</sup>
	Fabric filter inlet temperature ..	Maintain average fabric filter inlet temperature for each 3-hr period at or below average temperature during the performance test +14 °C (+25 °F).
	Lime injection rate .....	Maintain free-flowing lime in the feed hopper or silo at all times for continuous injection systems; maintain feeder setting at level established during the performance test for continuous injection systems.
Sweat furnace with afterburner	Afterburner operating temperature.	If a performance test was conducted, maintain average temperature for each 3-hr period at or above average operating temperature during the performance test; if a performance test was not conducted, and afterburner meets specifications of § 63.1505(f)(1), maintain average temperature for each 3-hr period at or above 1600 °F.
	Afterburner operation .....	Operate in accordance with OM&M plan. <sup>b</sup>
Dross-only furnace with fabric filter.	Bag leak detector or .....	Initiate corrective action within 1-hr of alarm and complete in accordance with the OM&M plan; <sup>b</sup> operate such that alarm does not sound more than 5% of operating time in 6-month period.
	COM .....	Initiate corrective action within 1-hr of a 6-minute average opacity reading of 5% or more and complete in accordance with the OM&M plan. <sup>b</sup>
	Feed/charge material .....	Operate using only dross as the feed material.
Rotary dross cooler with fabric filter.	Bag leak detector or .....	Initiate corrective action within 1-hr of alarm and complete in accordance with the OM&M plan; <sup>b</sup> operate such that alarm does not sound more than 5% of operating time in 6-month period.
	COM .....	Initiate corrective action within 1-hr of a 6-minute average opacity reading of 5% or more and complete in accordance with the OM&M plan. <sup>b</sup>
	Bag leak detector or .....	Initiate corrective action within 1-hr of alarm and complete in accordance with the OM&M plan; <sup>b</sup> operate such that alarm does not sound more than 5% of operating time in 6-month period.

Affected source/emission unit	Monitor type/operation/process	Operating requirements
In-line fluxer (using no reactive flux material). Group 1 furnace with lime-injected fabric filter (including those that are part of a secondary of aluminum processing unit)..	COM .....	Initiate corrective action within 1-hr of a 6-minute average opacity reading of 5% or more and complete in accordance with the OM&M plan. <sup>b</sup>
	Lime injection rate .....	Maintain free-flowing lime in the feed hopper or silo at all times for continuous injection systems; maintain feeder setting at level established during performance test for continuous injection systems.
	Reactive flux injection rate .....	Maintain reactive flux injection rate at or below rate used during the performance test for each operating cycle or time period used in the performance test.
	Flux materials .....	Use no reactive flux.
	Bag leak detector or	Initiate corrective action within 1-hr of alarm; operate such that alarm does not sound more than 5% of operating time in 6-month period; complete corrective action in accordance with the OM&M plan. <sup>b</sup>
	COM .....	Initiate corrective action within 1-hr of a 6-minute average opacity reading of 5% or more; complete corrective action in accordance with the OM&M plan. <sup>b</sup>
	Fabric filter inlet temperature ..	Maintain average fabric filter inlet temperature for each 3-hour period at or below average temperature during the performance test +14 °C (+25 °F).
	Reactive flux injection rate .....	Maintain reactive flux injection rate (kg/Mg) (lb/ton) at or below rate used during the performance test for each furnace cycle.
	Lime injection rate .....	Maintain free-flowing lime in the feed hopper or silo at all times for continuous injection systems; maintain feeder setting at level established at performance test for continuous injection systems.
	Maintain molten aluminum level.	Operate sidewall furnaces such that the level of molten metal is above the top of the passage between sidewall and hearth during reactive flux injection, unless the hearth is also controlled.
Group 1 furnace without add-on controls (including those that are part of a secondary aluminum processing unit).	Fluxing in sidewall furnace hearth.	Add reactive flux only to the sidewall of the furnace unless the hearth is also controlled.
	Reactive flux injection rate .....	Maintain reactive flux injection rate (kg/Mg) (lb/ton) at or below rate used during the performance test for each operating cycle or time period used in the performance test.
	Site-specific monitoring plan <sup>c</sup>	Operate furnace within the range of charge materials, contaminant levels, and parameter values established in the site-specific monitoring plan.
Clean (group 2) furnace .....	Feed material (melting/holding furnace).	Use only clean charge.
	Charge and flux materials .....	Use only clean charge. Use no reactive flux.

<sup>a</sup> Thermal chip dryers, scrap dryers/delacquering kilns/decoating kilns, dross-only furnaces, in-line fluxers and group 1 furnaces including melting/holding furnaces.

<sup>b</sup> OM&M plan—Operation, maintenance, and monitoring plan.

<sup>c</sup> Site-specific monitoring plan. Owner/operators of group 1 furnaces without control devices must include a section in their OM&M plan that documents work practice and pollution prevention measures, including procedures for scrap inspection, by which compliance is achieved with emission limits and process or feed parameter-based operating requirements. This plan and the testing to demonstrate adequacy of the monitoring plan must be developed in coordination with and approved by the permitting authority.

[65 FR 15710, Mar. 23, 2000, as amended at 67 FR 79818, Dec. 30, 2002; 69 FR 53984, Sept. 3, 2004]

TABLE 3 TO SUBPART RRR OF PART 63—SUMMARY OF MONITORING REQUIREMENTS FOR NEW AND EXISTING AFFECTED SOURCES AND EMISSION UNITS

Affected source/Emission unit	Monitor type/Operation/Process	Monitoring requirements
All affected sources and emission units with an add-on air pollution control device. All affected sources and emission units subject to production-based (lb/ton of feed/charge) emission limits <sup>a</sup> . Group 1 furnace, group 2 furnace, in-line fluxer, and scrap dryer/delacquering kiln/decoating kiln.	Emission capture and collection system.	Annual inspection of all emission capture, collection, and transport systems to ensure that systems continue to operate in accordance with ACGIH standards.
	Feed/charge weight .....	Record weight of each feed/charge, weight measurement device or other procedure accuracy of ±1% <sup>b</sup> ; calibrate according to manufacturers specifications, or at least once every 6 months.
	Labeling .....	Check monthly to confirm that labels are intact and legible.