

(g) Required Actions

Except as required by paragraph (h) of this AD, at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 717-55A0012, Revision 1, dated April 11, 2018, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 717-55A0012, Revision 1, dated April 11, 2018.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 717-55A0012, Revision 1, dated April 11, 2018, uses the phrase "the Revision 1 issue date of this service bulletin," this AD requires using the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 717-55A0012, Revision 1, dated April 11, 2018, specifies contacting Boeing, and specifies that action as RC: This AD requires repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Credit for Previous Actions

(1) This paragraph provides credit for the initial inspection specified in paragraph (g) of this AD, if that inspection was performed before June 8, 2016 (the effective date of AD 2016-09-05), using Boeing MOM-MOM-14-0437-01B(R1), dated July 3, 2014. This service information is not incorporated by reference in this AD.

(2) This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 717-55A0012, dated June 12, 2015. This service information was incorporated by reference in AD 2016-09-05.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization

Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2016-09-05 are approved as AMOCs for the corresponding provisions of Boeing Alert Service Bulletin 717-55A0012, Revision 1, dated April 11, 2018, that are required by paragraph (g) of this AD.

(5) Except as required by paragraph (h)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(5)(i) and (j)(5)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact: Muoi Vuong, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5205; fax: 562-627-5210; email: muoi.vuong@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 717-55A0012, Revision 1, dated April 11, 2018.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For

information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 8, 2018.

Jeffrey E. Duven,

Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-10413 Filed 5-15-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY**Coast Guard****33 CFR Part 165**

[Docket No. USCG-2018-0250]

Safety Zones; Fireworks and Swim Events in Captain of the Port New York Zone

AGENCY: Coast Guard, DHS.

ACTION: Notice of enforcement of regulation.

SUMMARY: The Coast Guard will enforce various safety zones within the Captain of the Port New York Zone on the specified dates and times. This action is necessary to ensure the safety of vessels, spectators and participants from hazards associated with fireworks. During the enforcement period, no person or vessel may enter the safety zones without permission of the Captain of the Port (COTP).

DATES: The regulation for the safety zones described in 33 CFR 165.160 will be enforced on the dates and times listed in the table below.

FOR FURTHER INFORMATION CONTACT: If you have questions regarding this document, call or email Petty Officer First Class Ronald Sampert U.S. Coast Guard; telephone 718-354-4197, email ronald.j.sampert@uscg.mil.

SUPPLEMENTARY INFORMATION: The Coast Guard will enforce the safety zones listed in 33 CFR 165.160 on the specified dates and times as indicated in Tables 1 and 2 below. This regulation was published in the **Federal Register** on November 9, 2011 (76 FR 69614).

TABLE 1

1. 2018 Ellis Island Medals of Honor (N.E.C.O.), Liberty Island Safety Zone, 33 CFR 165.160(2.1).	<ul style="list-style-type: none"> • Launch site: A barge located in approximate position 40°41'16.5" N 074°02'23" W (NAD 1983) located in Federal Anchorage 20–C, about 360 yards east of Liberty Island. This Safety Zone is a 360-yard radius from the barge. • Date: May 12, 2018. • Time: 11:30 p.m.–12:30 a.m.
2. Carnival Horizon Ship Christening, Pier 90 Hudson River Safety Zone, 33 CFR 165.160(5.4).	<ul style="list-style-type: none"> • Launch site: A barge located in approximate position 40°46'11.8"N, 074°00'14.8"W (NAD 1983) about 375 yards west of Pier 90. This Safety Zone is a 360-yard radius from the barge. • Date: May 23, 2018. • Time: 10:00 p.m.–10:30 p.m.
3. Marist College O.A.C.A.C., Poughkeepsie, NY, Hudson River Safety Zone, 33 CFR 165.160(5.13).	<ul style="list-style-type: none"> • Launch site: A barge located in approximate position 41°42'24.50" N, 073°56'44.16" W (NAD 1983), approximately 420 yards north of the Mid Hudson Bridge. This Safety Zone is a 300-yard radius from the barge. • Date: June 7, 2018. • Time: 8:30 p.m.–9:30 p.m.
4. Boston Consulting Group, Ellis Island Safety Zone, 33 CFR 165.160(2.2).	<ul style="list-style-type: none"> • Launch site: A barge located between Federal Anchorages 20–A and 20–B, in approximate position 40°41'45" N, 074°03'42" W (NAD 1983), about 260 yards south of Ellis Island. This Safety Zone is a 240-yard radius from the barge. • Date: June 8, 2018. • Time: 10:00 p.m.–10:30 p.m.

TABLE 2

5. Newburgh Beacon Swim, Safety Zone, 33 CFR 165.160(1.2)	<ul style="list-style-type: none"> • Location: Participants will cross the Hudson River between Newburgh, to Beacon, New York approximately 1300 yards south of the Newburgh-Beacon bridges. This Safety Zone includes all waters within a 100-yard radius of each participating swimmer. • Date: July 28, 2018. • Time: 09:00 a.m.–11:30 a.m.
---	---

Under the provisions of 33 CFR 165.160, vessels may not enter the safety zones unless given permission from the COTP or a designated representative. Spectator vessels may transit outside the safety zones but may not anchor, block, loiter in, or impede the transit of other vessels. The Coast Guard may be assisted by other Federal, State, or local law enforcement agencies in enforcing this regulation.

This document is issued under authority of 33 CFR 165.160(a) and 5 U.S.C. 552(a). In addition to the publication of this document in the **Federal Register**, the Coast Guard will provide mariners with advanced notification of enforcement periods via the Local Notice to Mariners and marine information broadcasts. If the COTP determines that a safety zone need not be enforced for the full duration stated in this notification, a Broadcast Notice to Mariners may be used to grant general permission to enter the safety zone.

Dated: April 27, 2018.

M.H. Day,
Captain, U.S. Coast Guard, Captain of the Port New York.

[FR Doc. 2018–10447 Filed 5–15–18; 8:45 am]

BILLING CODE 9110–04–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 80

[EPA–HQ–OAR–2018–0114; FRL–9977–50–OAR]

Removal of the Federal Reformulated Gasoline Program from the Northern Kentucky Portion of the Cincinnati-Hamilton Ozone Maintenance Area

AGENCY: Environmental Protection Agency (EPA).

ACTION: Notification of final action on petition.

SUMMARY: The Environmental Protection Agency (EPA) is taking final action in announcing its approval of the petition by Kentucky to opt-out of the federal reformulated gasoline (RFG) program and remove the requirement to sell federal RFG for Boone, Campbell, and Kenton counties (the Northern Kentucky Area), which are part of the Cincinnati-Hamilton, Ohio-Kentucky-Indiana maintenance area for the 2008 ozone national ambient air quality standard (NAAQS) (Cincinnati-Hamilton, OH-KY-IN Area). EPA has determined that this removal of the federal RFG program

for the Northern Kentucky Area is consistent with the applicable provisions of the Clean Air Act (CAA) and EPA’s regulations.

DATES: The effective date for removal of the Northern Kentucky Area from the federal RFG program is July 1, 2018.

FOR FURTHER INFORMATION CONTACT: David Dickinson, Office of Transportation and Air Quality, U.S. Environmental Protection Agency, 1200 Pennsylvania Avenue, Washington, DC 20460; telephone number: (202) 343–9256; email address: *dickinson.david@epa.gov* or Rudy Kapichak, Office of Transportation and Air Quality, U.S. Environmental Protection Agency, (2000 Traverwood, Ann Arbor, MI 48105); telephone number: 734–214–4574; email address: *kapichak.rudolph@epa.gov*.

SUPPLEMENTARY INFORMATION:

I. General Information

A. Does this action apply to me?

Entities potentially affected by this final action are fuel producers and distributors who do business in the Northern Kentucky Area.