#### **Comments Due Date**

(a) We must receive comments by December 2, 2011.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to CFM International, S.A. CFM56–5B1/3, CFM56–5B2/3, CFM56–5B3/3, CFM56–5B4/3, CFM56–5B5/3, CFM56–5B6/3, CFM56–5B6/3, CFM56–5B9/3, CFM56–5B9/3, CFM56–5B8/3, CFM56–5B4/3B1 engines equipped with fan blades P/N 338–002–114–0 that have a serial number (S/N) listed in Appendix A of CFM International Service Bulletin (SB) CFM56–5B S/B 72–0777, Revision 1, dated April 11, 2011.

#### **Unsafe Condition**

(d) This AD was prompted by a normal quality sampling at CFM that isolated a production batch of fan blades with nonconforming geometry of mid-span shroud tips of the fan blades. This defect would cause the upper panel of the fan blade to be liberated following foreign object damage (FOD) or a bird strike and likely result in an inflight shutdown (IFSD). We are proposing this AD to prevent an IFSD of one or more engines following FOD or a bird strike.

#### Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

#### Remove Fan Blades From Service

(f) For engines that have fan blades, P/N 338–002–114–0 with S/Ns listed in Appendix A of CFM International SB CFM56–5B S/B 72–0777, Revision 1, dated April 11, 2011, remove the fan blade from service within 5,000 flight hours after the effective date of this AD.

## **Installation Prohibition**

(g) After the effective date of this AD, do not install any fan blade, P/N 338–002–114–0 that has an S/N listed in Appendix A of CFM International SB CFM56–5B S/B 72–0777, Revision 1, dated April 11, 2011, onto any engine.

# Alternative Methods of Compliance (AMOCs)

(h) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

#### Related Information

(i) For more information about this AD, contact Carlos Fernandes, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781–238–7189; fax: 781–238–7199; e-mail: carlos.fernandes@faa.gov.

(j) For service information identified in this AD, contact CFM International, Inc., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; International Phone: 1–513–552–3272; USA Phone: 877–432–3272; International Fax: 1–513–552–3329; USA Fax: 877–432–3329; e-

mail: geae.aoc@ge.com; or CFM International SA, Customer Support Center, International Phone: 33 1 64 14 88 66; Fax: 33 1 64 79 85 55; e-mail: snecma.csc@snecma.fr. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781–238–7125.

Issued in Burlington, Massachusetts on October 6, 2011.

#### Peter A. White,

 $\label{lem:manager} \textit{Manager, Engine & Propeller Directorate,} \\ \textit{Aircraft Certification Service.}$ 

[FR Doc. 2011–26823 Filed 10–17–11; 8:45 am]

BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

## 14 CFR Part 71

[Docket No. FAA-2011-1057; Airspace Docket No. 11-AEA-21]

# Proposed Amendment of Class E Airspace; Huntington, WV

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E Airspace at Huntington, WV, as the Huntt Non-Directional Beacon (NDB) has been decommissioned and new Standard Instrument Approach Procedures (SIAPs) have been developed at Tri-State/Milton J Ferguson Field Airport. This action would enhance the safety and airspace management of Instrument Flight Rules (IFR) operations at the airport. This action also would update the geographic coordinates of the airport.

**DATES:** Comments must be received on or before December 2, 2011.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590–0001; Telephone: 1–800–647–5527; Fax: 202–493–2251. You must identify the Docket Number FAA–2011–1057; Airspace Docket No. 11–AEA–21, at the beginning of your comments. You may also submit and review received comments through the Internet at

http://www.regulations.gov.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636,

Atlanta, Georgia 30320; telephone (404) 305–6364.

#### SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2011–1057; Airspace Docket No. 11–AEA–21) and be submitted in triplicate to the Docket Management System (see ADDRESSES section for address and phone number). You may also submit comments through the Internet at http://www.regulations.gov.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA–2011–1057; Airspace Docket No. 11–AEA–21." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

# Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through http://www.regulations.gov. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports\_airtraffic/air\_traffic/publications/airspace\_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the ADDRESSES section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation

Administration, room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267–9677, to request a copy of Advisory circular No. 11–2A, Notice of Proposed Rulemaking distribution System, which describes the application procedure.

# The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class E airspace extending upward from 700 feet above the surface to support new Standard Instrument Approach Procedures developed at Tri-State/ Milton J Ferguson Field Airport, Huntington, WV. Airspace reconfiguration is necessary due to the decommissioning of the Huntt NDB and cancellation of the NDB approach, and for continued safety and management of IFR operations at the airport. The geographic coordinates of the airport also would be adjusted to coincide with the FAAs aeronautical database.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.9V, dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the

authority described in Subtitle VII, Part, A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This proposed regulation is within the scope of that authority as it would amend Class E airspace at Tri-State/Milton J Ferguson Field Airport, Huntington, WV.

## **Lists of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

# The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### §71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9V, Airspace Designations and Reporting Points, dated August 9, 2011, effective September 15, 2011, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

# AEA WV E Huntington, WV

Tri-State/Milton J. Ferguson Field Airport, Huntington, WV

(Lat. 38°22′02″N., long. 82°33′52″W.)

That airspace extending upward from 700 feet above the surface within an 8.2-mile radius of the Tri-State/Milton J Ferguson Field Airport.

Issued in College Park, Georgia, on October 5, 2011.

# Barry A. Knight,

Acting Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2011–26473 Filed 10–17–11; 8:45 am] BILLING CODE 4910–13–P

# ENVIRONMENTAL PROTECTION AGENCY

#### 40 CFR Part 112

[EPA-HQ-OPA-2011-0838; FRL-9481-3]

#### RIN 2050-AG59

Oil Pollution Prevention; Spill Prevention, Control, and Countermeasure (SPCC) Rule— Compliance Date Amendment for Farms

**AGENCY:** Environmental Protection Agency (EPA).

**ACTION:** Proposed rule.

SUMMARY: EPA is proposing to amend the date by which farms must prepare or amend, and implement their Spill Prevention, Control, and Countermeasure Plans, to May 10, 2013. In the "Rules and Regulations" section of this Federal Register, EPA is amending the date by which farms must prepare or amend, and implement their Spill Prevention, Control, and Countermeasure Plans to May 10, 2013, as a direct final rule without a prior proposed rule. If we receive no adverse comment, we will not take further action on this proposed rule.

**DATES:** Written comments must be received by November 2, 2011.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA-HQ-OPA-2011-0838, by mail to EPA Docket Center (EPA/DC), Environmental Protection Agency, Mailcode: 2822T, 1200 Pennsylvania Ave., NW., Washington, DC 20460. Comments may also be submitted electronically or through hand delivery/courier by following the detailed instructions in the ADDRESSES section of the direct final rule located in the rules section of this Federal Register.

FOR FURTHER INFORMATION CONTACT: For general information, contact the Superfund, TRI, EPCRA, RMP and Oil Information Center at (800) 424–9346 or TDD (800) 553-7672 (hearing impaired). In the Washington, DC metropolitan area, call (703) 412-9810 or TDD (703) 412–3323. For more detailed information on specific aspects of this final rule, contact either Lynn Beasley at (202) 564–1965 (beasley.lynn@epa.gov) or Mark W. Howard at (202) 564-1964 (howard.markw@epa.gov), U.S. Environmental Protection Agency, 1200 Pennsylvania Avenue, NW., Washington, DC 20460-0002, Mail Code 5104A.

# SUPPLEMENTARY INFORMATION: