

## § 1915.90

(3) Inspect the machinery, equipment, or system and the immediate area around the machinery, equipment, or system to ensure that nonessential items have been removed and that the machinery, equipment or system components are operationally intact.

(4) Reconnect the necessary components, remove the lockout/tags-plus material and hardware, and reenergize the machinery, equipment, or system through the established detailed procedures determined by the employer.

(5) Notify all affected employees that servicing is complete and the machinery, equipment, or system is ready for testing or use.

### § 1915.90 Safety color code for marking physical hazards.

The requirements applicable to shipyard employment under this section are identical to the requirements set forth at 29 CFR 1910.144 of this chapter.

### § 1915.91 Accident prevention signs and tags.

The requirements applicable to shipyard employment under this section are identical to the requirements set forth at 29 CFR 1910.145 of this chapter.

### § 1915.92 Retention of DOT markings, placards, and labels.

(a) Any employer who receives a package of hazardous material that is required to be marked, labeled, or placarded in accordance with the U.S. Department of Transportation Hazardous Materials Regulations (49 CFR parts 171 through 180) shall retain those markings, labels, and placards on the package until the packaging is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.

(b) Any employer who receives a freight container, rail freight car, motor vehicle, or transport vehicle that is required to be marked or placarded in accordance with the U.S. Department of Transportation Hazardous Materials Regulations shall retain those markings and placards on the freight container, rail freight car, motor vehicle, or transport vehicle until the hazardous materials are sufficiently removed to prevent any potential hazards.

(c) The employer shall maintain markings, placards, and labels in a manner that ensures that they are readily visible.

## 29 CFR Ch. XVII (7–1–12 Edition)

(d) For non-bulk packages that will not be reshipped, the requirements of this section are met if a label or other acceptable marking is affixed in accordance with 29 CFR 1910.1200, Hazard Communication.

(e) For the purposes of this section, the term “hazardous material” and any other terms not defined in this section have the same definition as specified in the U.S. Department of Transportation Hazardous Materials Regulations.

### § 1915.93 Motor vehicle safety equipment, operation and maintenance.

(a) *Application.* (1) This section applies to any motor vehicle used to transport employees, materials, or property at worksites engaged in shipyard employment. This section does not apply to motor vehicle operation on public streets and highways.

(2) The requirements of this section apply to employer-provided motor vehicles. The requirements of paragraphs (b)(2), (b)(4), and (c)(2) of this section also apply to employee-provided motor vehicles.

(3) Only the requirements of paragraphs (b)(1) through (b)(3) apply to powered industrial trucks, as defined in § 1910.178. The maintenance, inspection, operation, and training requirements in 29 CFR 1910.178 continue to apply to powered industrial trucks used for shipyard employment.

(b) *Motor vehicle safety equipment.* (1) The employer shall ensure that each motor vehicle acquired or initially used after August 1, 2011 is equipped with a safety belt for each employee operating or riding in the motor vehicle. This requirement does not apply to any motor vehicle that was not equipped with safety belts at the time of manufacture.

(2) The employer shall ensure that each employee uses a safety belt, securely and tightly fastened, at all times while operating or riding in a motor vehicle.

(3) The employer shall ensure that vehicle safety equipment is not removed from any employer-provided vehicle. The employer shall replace safety equipment that is removed.

(4) The employer shall ensure that each motor vehicle used to transport