

(3) The alternative procedure may include prime contractor release of supplies inspected at a subcontractor's facility.

(4) The use of the alternative procedure releases DoD manpower to perform technical functions by eliminating routine signing or stamping of the papers accompanying each shipment.

(b) *Alternative Procedures—Contract Release for Shipment.* (1) The contract administration office may authorize, in writing, the contractor to release supplies for shipment when—

(i) The stamping or signing of the shipping papers by a representative of the contract administration office interferes with the operation of the Government contract quality assurance program or takes too much of the Government representative's time;

(ii) There is sufficient continuity of production to permit the Government to establish a systematic and continuing evaluation of the contractor's control of quality; and

(iii) The contractor has a record of satisfactory quality, including that pertaining to preparation for shipment.

(2) The contract administration office shall withdraw, in writing, the authorization when there is an indication that the conditions in paragraph (b)(1) of this subsection no longer exist.

(3) When the alternative procedure is used, require the contractor to—

(i) Type or stamp, and sign, the following statement on the required copy or copies of the shipping paper(s), or on an attachment—

The supplies in this shipment—

1. Have been subjected to and have passed all examinations and tests required by the contract;

2. Were shipped in accordance with authorized shipping instructions;

3. Conform to the quality, identity, and condition called for by the contract; and

4. Are of the quantity shown on this document.

This shipment was—

1. Released in accordance with section 246.471 of the Defense FAR Supplement; and

2. Authorized by (name and title of the authorized representative of the contract administration office) in a letter dated (date of authorizing letter). (Signature and title of contractor's designated official.)

(ii) Release and process, in accordance with established instructions, the DD Form 250, Material Inspection and Receiving Report, or other authorized receiving report.

#### **246.472 Inspection stamping.**

(a) DoD quality inspection approval marking designs (stamps) may be used for both prime contracts and subcontracts. Follow the procedures at PGI 246.472(a) for use of DoD inspection stamps.

(b) Policies and procedures regarding the use of National Aeronautics and Space Administration (NASA) quality status stamps are contained in NASA publications. When requested by NASA centers, the DoD inspector shall use NASA quality status stamps in accordance with current NASA requirements.

[71 FR 27647, May 12, 2006]

### **Subpart 246.5—Acceptance**

#### **246.504 Certificate of conformance.**

Before authorizing a certificate of conformance for aviation or ship critical safety items, obtain the concurrence of the head of the design control activity (see 209.270).

[73 FR 1828, Jan. 10, 2008]

### **Subpart 246.6—Material Inspection and Receiving Reports**

#### **246.601 General.**

See Appendix F, Material Inspection and Receiving Report, for procedures and instructions for the use, preparation, and distribution of—

(1) The Material Inspection and Receiving Report (DD Form 250 series); and

(2) Supplier's commercial shipping/packing lists used to evidence Government contract quality assurance.

[71 FR 27647, May 12, 2006]

### **Subpart 246.7—Warranties**

#### **246.701 Definitions as used in this subpart.**

*Acceptance* as used in this subpart and in the warranty clauses at FAR 52.246-17, Warranty of Supplies of a Noncomplex Nature; FAR 52.246-18,