Environmental Protection Agency

recyclable materials. The plan must identify any additional waste management measures, and the source must implement those measures considered practical and feasible, based on the effectiveness of waste management measures already in place, the costs of additional measures, the emissions reductions expected to be achieved, and any other environmental or energy impacts they might have.

OPERATOR TRAINING AND QUALIFICATION

§ 62.14595 What are the operator training and qualification requirements?

- (a) You must have a fully trained and qualified CISWI unit operator accessible at all times when the unit is in operation, either at your facility or able to be at your facility within one hour. The trained and qualified CISWI unit operator may operate the CISWI unit directly or be the direct supervisor of one or more other plant personnel who operate the unit. If all qualified CISWI unit operators are temporarily not accessible, you must follow the procedures in §62.14625.
- (b) Operator training and qualification must be obtained through a State-approved program or by completing the requirements included in paragraph (c) of this section.
- (c) Training must be obtained by completing an incinerator operator training course that includes, at a minimum, the three elements described in paragraphs (c)(1) through (3) of this section
- (1) Training on the thirteen subjects listed in paragraphs (c)(1)(i) through (xiii) of this section.
- (i) Environmental concerns, including types of emissions.
- (ii) Basic combustion principles, including products of combustion.
- (iii) Operation of the specific type of incinerator to be used by the operator, including proper startup, waste charging, and shutdown procedures.
- (iv) Combustion controls and monitoring.
- (v) Operation of air pollution control equipment and factors affecting performance (where applicable).
- (vi) Inspection and maintenance of the incinerator and air pollution control devices.

- (vii) Actions to correct malfunctions or conditions that may lead to malfunction.
- (viii) Bottom and fly ash characteristics and handling procedures.
- (ix) Applicable Federal, State, and local regulations, including Occupational Safety and Health Administration workplace standards.
 - (x) Pollution prevention.
 - (xi) Waste management practices.
 - (xii) Recordkeeping requirements.
- (xiii) Methods to continuously monitor CISWI unit and air pollution control device operating parameters and monitoring equipment calibration procedures (where applicable).
- (2) An examination designed and administered by the instructor.
- (3) Written material covering the training course topics that can serve as reference material following completion of the course.

§ 62.14600 When must the operator training course be completed?

- (a) The operator training course must be completed by the later of the two dates specified in paragraphs (a)(1) and (2) of this section.
 - (1) October 4, 2004.
- (2) Six months after an employee assumes responsibility for operating the CISWI unit or assumes responsibility for supervising the operation of the CISWI unit.
- (b) You must follow the requirements in §63.14625 if all qualified operators are temporarily not accessible.

§62.14605 How do I obtain my operator qualification?

- (a) You must obtain operator qualification by completing a training course that satisfies the criteria under §62.14595(b) or (c).
- (b) Qualification is valid from the date on which the training course is completed and the operator successfully passes the examination required under $\S62.14595(c)(2)$.

§ 62.14610 How do I maintain my operator qualification?

To maintain qualification, you must complete an annual review or refresher course of at least 4 hours covering, at a minimum, the five topics described in