

Unsafe Condition

(d) This AD results from reports of cracks found at the anchor tab of the bulkhead seal assemblies of the wing thermal anti-ice (TAI) system. In one incident, the anchor tab and bulkhead seal assembly had separated because of the cracks. We are issuing this AD to prevent failure of the anchor tab of the bulkhead seal assembly, which in icing conditions could result in insufficient airflow to the wing TAI system, subsequent ice on the wings, and consequent reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Repetitive Inspections/Corrective Action

(f) At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 757-30-0021 or 757-30-0022, both Revision 1, both dated June 13, 2007, as applicable; except where the service bulletins specify starting the compliance time " * * * from the date on this service bulletin," this AD requires starting the compliance time from the effective date of this AD: Perform detailed inspections for cracks of the anchor tab of the bulkhead seal assemblies of the wing TAI system at certain outboard stations of the left and right wings by doing all the actions, including all applicable corrective actions, in accordance with the Accomplishment Instructions of the applicable service bulletin. Do all applicable corrective actions before further flight.

Optional Terminating Action

(g) Installing a new duct anchor support bracket adjacent to the bulkhead seal assemblies in accordance with Part 2 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 757-30-0021 or 757-30-0022, both Revision 1, both dated June 13, 2007, as applicable, ends the repetitive inspections required by paragraph (f) of this AD.

Credit for Actions Done According to Previous Issue of Service Information

(h) Actions accomplished before the effective date of this AD in accordance with Boeing Special Attention Service Bulletins 757-30-0021 and 757-30-0022, both dated August 15, 2006, are considered acceptable for compliance with the corresponding actions specified in this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District

Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(j) You must use Boeing Special Attention Service Bulletin 757-30-0021, Revision 1, dated June 13, 2007; or Boeing Special Attention Service Bulletin 757-30-0022, Revision 1, dated June 13, 2007; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 3, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7662 Filed 4-11-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2008-0203; Airspace Docket No. 08-ANE-99]

Modification of Class D Airspace; Brunswick, ME

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule, request for comments.

SUMMARY: This action modifies Class D Airspace at Brunswick, ME. The Brunswick NAS Air Traffic Control Tower has become a part-time facility; therefore, the Class D Airspace associated with the tower operations must be modified to reflect part-time status. This action enhances the National Airspace System by replacing a more restricted airspace area with a less restrictive one at Brunswick, ME.

DATES: Effective 0901 UTC, June 5, 2008. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order

7400.9 and publication of conforming amendments. Comments for inclusion in the Rules Docket must be received on or before May 29, 2008.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2008-0203; Airspace Docket No. 08-ANE-99, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

You may review the public docket containing the rule, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room 210, 1701 Columbia Avenue, College Park, Georgia 30337.

FOR FURTHER INFORMATION CONTACT:

Melinda Giddens, System Support Group, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; Telephone (404) 305-5610, Fax 404-305-5572.

SUPPLEMENTARY INFORMATION:**The Direct Final Rule Procedure**

The FAA anticipates that this regulation will not result in adverse or negative comments, and, therefore, issues it as a direct final rule. The FAA has determined that this rule only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Unless a written adverse or negative comment or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the effective date. If the FAA receives, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a direct final rule, and was not preceded by a notice of proposed rulemaking, interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. The direct final rule is used in this case to facilitate the timing of the charting schedule and enhance the operation at the airport, while still allowing and requesting public comment on this rulemaking action. An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Communications should identify both docket numbers and be submitted in triplicate to the address specified under the caption **ADDRESSES** above or through the website. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the **Federal Register's** Web page at <http://www.gpoaccess.gov/fr/index.html>.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action would be needed. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. Those wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2008-0203; Airspace Docket No. 08-ANE-99." The postcard will be date stamped and returned to the commenter.

The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 modifies Class D airspace at Brunswick, ME, providing the controlled airspace required to support the hours of operation of the Air Traffic Control Tower at Brunswick NAS Airport. Controlled airspace extending upward from the surface of the Earth is required to encompass all SIAPs to the extent

practical and for general Instrument Flight Rule (IFR) operations. The current Class D airspace in the area is sufficient for these approaches, so no additional controlled airspace must be developed. Class D airspace times will be published first by Notice to Airman, then thereafter published continuously in the Airport/Facility Directory. The FAA is amending Title 14, Code of Federal Regulations (14 CFR) part 71 by modifying the Class D airspace description at Brunswick NAS to reflect its part time Air Traffic Control Tower's operation. Designations for Class D airspace areas extending upward from the surface of the Earth are published in FAA Order 7400.9R, signed August 15, 2007 effective September 15, 2007, which is incorporated by reference in 14 CFR part 71.1. The Class D designations listed in this document will be published subsequently in the Order.

Agency Findings

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section

40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies controlled airspace at Brunswick, ME.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9R, Airspace Designations and Reporting Points, signed August 15, 2007, effective September 15, 2007, is amended as follows:

Paragraph 5000 Class D Airspace.

* * * * *

ANE ME D Brunswick, ME [Revised]

Brunswick NAS Airport,

(Lat. 43°53'32" N., long 69°56'19" W.)

That airspace extending upward from the surface of the Earth to and including 2,600 feet MSL within a 4.3-mile radius of Brunswick NAS. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in College Park, Georgia, on March 21, 2008.

Mark D. Ward,

Manager, System Support Group, Eastern Service Center.

[FR Doc. E8-7694 Filed 4-11-08; 8:45 am]

BILLING CODE 4910-13-M