


Exposed electrical system and rain damage in an operational facility




Exposed electrical system and rain damage in an operational facility



Makeshift Central Control Station with exposed wiring. This Central Control was created within an existing Booking space. Picture indicates the unreliable door control console to the left




Exposed and overloaded wiring at the Central Control Station



Exposed wiring raceway and an filled to overcapacity raceway for the security camera monitors




Exposed wiring




Exposed wiring

**5 - Emergency Egress is a challenge**

Facilities lack appropriate egress. An electrical outage during an emergency is detrimental to the safety and security of the inmates and officers. In an emergency, inmates cannot be alerted within one minute and evacuated within three minutes, to a secured location.



Blocked Exit




Known inoperative door lock switches




Partially inoperative Door Lock Operators Console




Inoperative manual override for electrical cell-door lock switches




Locked cell doors without mechanical override




Locked cell doors without mechanical override



Locked cell doors without mechanical override.




Locked cell doors without mechanical override



Blocked Exit door


Emergency Egress




Exit door from above picture, without appropriate steps to egress



Locked cell doors without mechanical override



Locked cell doors without a mechanical override.



Locked cell doors without a mechanical override.

**6 - Environmental Challenges**

**Unaware of environmental effects, facilities face continuing environmental challenges**

DRAFT



Growing mold



Oil dumped after continued oil changes



Operations as a car repair garage