




Extension cord in a day room used for a circulating fan for air circulation




Extension cord in a day room used for a pedestal fan for air circulation

**13 - Plumbing Challenges**

**Deteriorated plumbing lines and plumbing fixtures are a constant challenge in every facility except for the very new facilities.**

DRAFT




Water leak buckets in a staff restroom




Inoperative combination sink-toilet unit



Condensate water overflow from the roof HVAC unit



Close-up of picture above




Dribble from sink-toilet combination unit



Dribble from sink-toilet combination unit



Dribble from sink-toilet combination unit



Drinking water for inmates




Inoperative toilets at the officer's restroom



Plugged drains at the sink-toilet combination unit




Plugged drains at the sink-toilet combination unit



Water Leaks for the washer and dryer lines




Drinking water supply for the inmates




Missing hot water recirculation pump for over a year for the hot water to the women's showers



Out of service sink-toilet combination units



Circulation pump removed but not replaced for long enough duration to cause excessive buildup of corrosion



Makeshift cloth plugs to prevent leaks




Makeshift cloth plugs to prevent leaks

**14 - Recreation Yard Challenges**

**Most facilities have stopped providing outdoor time to inmates because of dysfunctional recreation yards. These yards are now used for other purposes and are a risk to the safety and security of inmates and officers.**

DRAFT

Recreation Yard Challenges



Recreation yard used as storage areas



Clothes drying lines in the recreation yard. Used as a substitute for a commercial dryer for bulky blankets.

Recreation Yard Challenges



Recreation yard is used for evidence storage